



U.S. Department of Transportation

National Highway Traffic Safety Administration

Dear Crash Data Researchers/Users:

Thank you for choosing crash data from the National Highway Traffic Safety Administration (NHTSA) for your research or other use. The information contained in this motor vehicle crash report is collected, maintained and distributed in accordance with Public Law 89-564. In accordance with this Public Law, NHTSA is required not to release any case information until completion of quality control procedures. These procedures include a review of the case material to extract all names, licenses and registration numbers, non-coded interview material, non-research related researcher comments in the margins, non-factual data, and the production number portion of the vehicle identification number (VIN).

If you requested NHTSA to query its database files in order to identify a specific crash, then that query was made using non-personal descriptors you provided for use in our search. This motor vehicle crash may have been identified from a data search and matches the general, non-personal descriptors you provided, but we cannot confirm that this is the specific crash report you requested.

If you have any questions with regard to the above procedures, please contact the Field Operations Branch, Crash Investigation Division, National Center for Statistics and Analysis at 202-366-4820. Again, please be advised that we cannot confirm that this is the case that you have specifically requested nor can we certify the information to be correct.

*** *** ***



Case Vehicle (A): 1999 Dodge

Vehicle (B): 1978 International Type: Dakota Sport, 4x2 regular cab pickup Type: COF Transtar 6x4 farm truck

Driver: 61-year-old female Driver: 32-year-old male

CDC: 11-FDEW-3 CDC: 99-0000-0

SITUATION

(Slides 1, 2) On a cloudy, dry day, case vehicle (A) was traveling east in a rural area at an unknown speed in the eastbound lane of a two-lane asphalt road, and was approaching an intersection with a gravel road, following a curve to the right. The gravel road connects to the asphalt road on a sharp angle and is equipped with a stop sign. (Slide 3) Vehicle (B) was traveling west in the westbound lane of the same asphalt roadway. The driver of vehicle (B) slowed down, and began making a left turn to travel southeast on the gravel road. (Slide 4) Case vehicle (A) had just completed the curve, when she saw vehicle (B) crossing her lane. (Slides 5, 6) The driver of case vehicle (A) braked, as indicated by a 25-meter right-front tire skid mark and a 14-meter left-front tire skid mark. She also steered slightly to the right, but was unable to keep her vehicle from striking the right side of vehicle (B) with its front end.

GENERAL VEHICLE DAMAGE AND ESTIMATED CRASH SEVERITIES

(Slides 7, 8) The direct damage to case vehicle (A) began at the left-front bumper corner and extended 162 cm across the entire front end. The maximum crush was 61 cm to the center portion of the front bumper.

Using the WinSMASH accident-reconstruction program and c-values measured for (slides 9, 10, 11, 12 and 13) case vehicle (A), the following impact severity was calculated:

		Calculated Velocity Change - kph (mph)			
Vehicle	Variable	Total	Longitudinal	Latitudinal	
Case Vehicle (A)	EBS	34 (21)	-34 (-21)	6 (4)	

DESCRIPTION OF DAMAGE TO CASE VEHICLE (A)

Exterior

(Slide 14) The front bumper was crushed, the grille was damaged, and both headlight assemblies were broken. (Slides 15, 16 and 17) The hood was crushed, the hood latch was damaged, and both rear hood hinges were deformed, but not separated. (Slide 18) The rear edge of the hood was elevated, but it did not contact the windshield. (Slide 19) There was no damage to the windshield.

(Slides 20, 21) On the left side, the fender was damaged and displaced to the right. (Slides 22, 23) There was no other damage to the left side of case vehicle (A), and no change in the left wheelbase.

(Slides 24, 25) On the right side, the fender was deformed and shifted slightly to the right, and the right-front wheel was damaged. (Slides 26, 27) There was no other damage to the right side and no change in the right wheelbase. (Slide 28) There was no rear-end damage.

Interior

This vehicle is equipped with steering-wheel and passenger frontal-impact airbags. The steering-wheel airbag deployed, but the passenger airbag was shut off and did not deploy. (Slide 29) There was blood on the steering-wheel airbag. (Slides 30, 31) The upper half of the steering-wheel rim was slightly deformed due to driver contact, and the steering column was rotated up and to the left. (Slide 32) The driver-side sunvisor was bent, and there was a scuff mark and blood on the sunvisor, indicating driver contact. (Slide 33) There was no damage to, and no contact marks on, the windshield, roofrail, or roof area. (Slides 34, 35) There were scuff marks on the upper and mid portions of the instrument panel, in addition to damage to the mid panel. (Slides 36, 37) There were scuff marks on, and damage to, the left portion of the knee bolster and the parking brake release knob. (Slide 38) Also, the accelerator and brake pedal were bent to the left. (Slides 39, 40) There was no damage to the center dash area or the glove compartment. There was no other interior damage. (Slide 41) The following intrusion was noted and measured:

Location	Component	Distance (cm)	Direction
left front	floor	6	up

OCCUPANT KINEMATICS AND INJURIES

(Slides 42, 43) The 5-ft, 4-in, 120-lb, 61-year-old female driver was <u>not</u> wearing the three-point belt and the airbag deployed. (Slides 44, 45 and 46) There was no physical evidence of belt use on the D-ring, seatbelt hardware, or the belt webbing. The driver reported braking with her right foot at the time of the crash.

During the impact, she continued forward relative to the vehicle interior, into and over the airbag. (Slide 47) She sustained a contusion to her forehead, probably from contact with the sunvisor, as indicated by damage, scuff marks, and blood on the sunvisor. (Slides 48, 49) In addition, she sustained two left rib fractures, possibly from contact with the steering wheel, or from loading by the deploying airbag. These fractured ribs punctured and lacerated her left lung, resulting in pneumothorax. (Slides 50, 51) She sustained a fracture to her left patella, left tibia and left fibula, from contact with the knee bolster and the parking-brake release handle, as indicated by scuff marks and damage to the left portion of the bolster cover and handle. (Slides 52, 53) She also sustained a fracture to her right ankle due to contact with the brake pedal.

The following table and attached drawing (slide 54) summarize the injuries for the driver.

Occupant: Driver Restraints: 3-point belt <u>not</u> worn; airbag deployed

Age: 61 years Stature: 163 cm (5 ft, 4 in)


Gender: Female Mass: 54 kg (120 lb)

,			Injury Source		
Injury Description	A.I.S.	Definite	Probable	Possible	
Contusion, forehead	1		Sunvisor		
Two left rib fractures	2			Steering wheel, airbag	
Left lung laceration with pneumothorax	3	Fractured ribs		Steering wheel, airbag	
Fracture, left patella	2		Knee bolster, parking- brake release handle		
Fracture, left tibia and fibula	2		Knee bolster, parking- brake release handle		
Fracture, right ankle	2		Brake pedal		
1					
Maximum A.I.S. Level	3				
Injury Severity Score	14	·			

Duplicate columns 1-8 Module G I Format from the previous card.	GENERAL INFORMATION	GI-1	
TIME DATE OF COLLISION m m/d d/y y HOUR OF COLLISION	ENVIRONMENTAL CONDITIONS CONSTRUCTION ZONE (0) NO (1) YES (9) UNKNOWN	<u>O</u>	
(24 HOUR CLOCK) 21 2 LOCATION STATE:	24	ROAD ALIGNMENT VERTICAL PLANE (1) LEVEL (2) CREST OF HILL (3) SLOPE (2%) (4) BOTTOM OF HILL (9) UNKNOWN	4/34
STATE FIPS CODE AREA (1) URBAN (2) RURAL (9) UNKNOWN	25 - 26 27	ROAD ALIGNMENT HORIZONTAL PLANE (1) STRAIGHT (2) CURVE (3) T - SHAPED (4) Y - SHAPED (7) OTHER: (9) UNKNOWN	3 35
ENVIRONMENTAL CONDITIONS LIMITED-ACCESS HIGHWAY (0) NO (1) YES (9) UNKNOWN ROAD, TOTAL TRAFFIC LANES (FOR CASE VEHICLE)	<u>O</u> 28	SURFACE COVERING (10) DRY (21) WATER - DAMP (22) WATER - WET (23) WATER - PUDDLED (29) WATER - AMOUNT UNKNOWN	<u>36</u> 37
(FOR CASE VEHICLE) (1) 1-LANE (2) 2-LANES (3) 3-LANES (4) 4 OR MORE LANES (5) DIVIDED, 4 OR MORE LANES (6) PARKING LOT/DRIVEWAY (7) OTHER: (9) UNKNOWN	2 29	(31) SNOW - LOOSE (32) SNOW - PACKED (39) SNOW - CONDITION UNKNOWN (41) ICE (51) SLUSH (61) SPILLED GRAVEL (71) OTHER: (99) UNKNOWN	
INTERSECTING RD, TOTAL LANES CHOOSE FROM ABOVE LIST, OR (8) NOT APPLICABLE TYPE OF ROAD SURFACE (1) ASPHALT (2) CONCRETE (3) GRAVEL (4) MORE THAN ONE (CIRCLE EACH) (7) OTHER: (9) UNKNOWN	30	VISIBILITY LIMITATION (FOR CASE VEHICLE) (0) NONE (1) CLOUDY/DARK (2) FOG (3) SMOKE (4) WINDSHIELD CONDITION (5) GLARE (6) RAIN (7) OTHER: (8) ICE/SNOW (9) UNKNOWN VISIBILITY OBSTRUCTION (FOR CASE VEHICLE)	<u>O</u> 38
(9) UNKNOWN ROAD DEFECTS (0) NO (1) YES (9) UNKNOWN	<u>O</u>	(0) NONE (1) BUILDING (2) SIGN (3) VEGETATION (E.G. BUSHES, SHRUBS) (4) TREE (5) HILL OR CURVE IN ROAD (6) VEHICLE IN TRANSPORT (7) OTHER: (8) PARKED VEHICLE (9) UNKNOWN	<u>⊘</u> 39

GENERAL INFORMATION GI-2					
ENVIRONMENTAL CONDITIONS SPEED LIMIT (0) 5-45 km/h 5-25 mph (1) 46-55 30 (2) 56-60 35 (3) 61-70 40 (4) 71-79 45 (5) 80-85 50 (6) 86-90 55 (7) 91-105 60 (8) OVER 105 65 (9) UNKNOWN	6	MECHANICAL MALFUNCTION WAS THERE MENTION OF A MECHANICAL MALFUNCTION IN CASE VEHICLE (0) NO (1) YES (2) YES, DID NOT CONTRIBUTE TO ACCIDENT (9) UNKNOWN			
(0) NONE (1) RAIN (2) SNOW (3) HAIL (4) FREEZING RAIN/SLEET (7) OTHER: (9) UNKNOWN RATE OF PRECIPITATION (1) LIGHT/MIST (2) MODERATE (3) HEAVY (8) NOT APPLICABLE (9) UNKNOWN TEMPERATURE (0) BELOW -15° C BELOW 5° F (1) -15 TO -6	Ø 41	THE FOLLOWING SECTION SHOULD BE FILLED OUT IF A MECHANICAL MALFUNCTION IS RECOGNIZED OR SUSPECTED. CIRCLE ITEMS INVOLVED. SUPPORT ANY ITEMS CIRCLED WITH COMMENTS. BRAKE SYSTEM DRIVER CONTROLS EXHAUST SYSTEM POWER TRAIN STEERING SYSTEM FUEL SYSTEM SUSPENSION SYSTEM VISIBILITY ITEMS ELECTRICAL SYSTEM TIRES THROTTLE CONTROLS UNKNOWN OTHER: COMMENTS:			
CROSSWIND (0) NONE (1) LIGHT (2) STRONG (3) GUSTY & STRONG (9) UNKNOWN LIGHT CONDITIONS (1) DAYLIGHT (2) DAWN (3) DUSK (4) DARK, LIGHTED (5) DARK, UNLIGHTED (6) DARK, UNKNOWN IF LIGHTED (9) UNKNOWN	44				
CLOUDY					


-			
		GENERAL INFORMATION	GI-3
CRASH DETAILS CASE VEHICLE AND OBJECT (0) NO (1) YES (9) UNKNOWN	47	(0) O - NO INJURY (1) C - POSSIBLE INJURY (2) B - NON-INCAPACITATING INJURY (3) A - INCAPACITATING INJURY	
CASE VEHICLE ROLLOVER (0) NO ROLLOVER (1) YES, FIRST EVENT (2) YES, SUBSEQUENT EVENT (3) YES, SEQUENCE UNKNOWN (9) UNKNOWN	<u>O</u>	(4) K - FATAL (5) INJURED, SEVERITY UNKNOWN (6) DIED PRIOR TO ACCIDENT (7) NON-FATAL INJURY SEVERITY UNKNOWN (9) UNKNOWN	3
CASE VEHICLE RAN OFF ROADWAY (BEFORE FIRST IMPACT) (0) NO (1) YES (9) UNKNOWN	<u>Ø</u>	DRIVER IMPAIRMENT DRIVER ALCOHOL INVOLVEMENT (CASE VEHICLE) (0) NONE (1) YES (9) UNKNOWN/NOT REPORTED/ NO DRIVER	<u></u>
MOVING CASE VEHICLE AND CONTACTED MOVING VEHICLE (0) NO (1) YES (9) UNKNOWN		DRIVER ALCOHOL BAC (CASE VEHICLE) (80) NO TEST (90) CHEMICAL TESTS, NO RESULTS (95) AUTOPSY, NO RESULTS (99) UNKNOWN	8 0 57 58
CASE VEHICLE AND CONTACTED STOPPED VEHICLE (0) NO (1) YES (9) UNKNOWN	51	WAS THERE MENTION OF DRIVER IMPAIRMENT FOR CASE VEHICLE? (0) NO (1) YES (9) UNKNOWN	<u>O</u> 59
STOPPED CASE VEHICLE AND CONTACTED VEHICLE (0) NO (1) YES (9) UNKNOWN	<u>O</u> 52	LIST IMPAIRMENTS MENTION	ED:
TOTAL NUMBER OF VEHICLES CONTACTED BY CASE VEHICLE IN CRASH (8) 8 OR MORE (9) UNKNOWN	53	Post - Crash Detail MANNER CASE VEHICLE LEFT SCENE	
ANY FIRE IN THIS CRASH (NOT JUST CASE VEHICLE) (0) NO H) YES (9) UNKNOWN	54	(1) DRIVEN (2) TOWED DUE TO DAMAGE (3) TOWED, NOT DUE TO DAMAGE (4) TOWED, REASON UNKNOWN (9) UNKNOWN	2 -



Duplicate columns 1-8 Module O V Format from the previous card.	1 0 4		OTHER VEHICLE	OV-1
MAKE: INTERNATIONAL			CARGO: SILACE	
MODEL: COF TRANSTAR	6 x4	FARM TO		
VIN <u>E 2 3 1 7 H G</u>	A	94		
MANUFAC/BODY CODE 1 53	37	VEHIC	LE TYPE	
MAKE/MODEL CODE 35	<u>97</u>	(02) (03)	IGER VEHICLE LARGE LIMOUSINE PICKUP CAR	37
MODEL YEAR	7 8	(20) (24) (25)	UNKNOWN PASSENGER VEHICLE BODY SUB-MINI	
VEHICLE MASS (kg) 9 9 9 9	7 9	(27) (28)	COMPACT INTERMEDIATE FULL	
IF SEPARATE REPORT WAS MADE, GIVE VEHICLE NUMBER	_0	(14)	JRPOSE PASSENGER VEHICLE SMALL UTILITY (WHEELBASE LESS THAN 107°, E.G. JEEP, BRONCO) LARGE UTILITY (WHEELBASE MORE THAN 107°,	
NUMBER OF OCCUPANTS (ENTER 9'S IF UNKNOWN)	<u> </u>	(16) (17) (21) (22) (23) (E.G. PANEL TRUCK, SUBURBAN) PICKUP TRUCK WITH CANOPY/SHELL COVER PICKUP CAR WITH CANOPY/SHELL COVER MOTOR HOME PICKUP TRUCK WITH SLIDE-IN CAMPER PICKUP CAR WITH SLIDE-IN CAMPER	
TRAVELING SPEED (km/h)	9	(31)	CHASSIS-MOUNTED CAMPER	
(000) PARKED OR STOPPED (995) JUST STARTING UP (996) BACKING UP (997) SPEED NOT EXCESSIVE (BUT UNKNOWN (998) SPEED EXCESSIVE (BUT UNKNOWN) (999) UNKNOWN	54	(13) U (15) L (16) F (22) F (30) U (31) C	VAN PICKUP TRUCK JNKNOWN LIGHT TRUCK ARGE UTILITY (E.G. PANEL TRUCK, SUBURBAN) PICKUP TRUCK WITH CANOPY/SHELL COVER PICKUP TRUCK WITH SLIDE-IN CAMPER JNKNOWN TRUCK TYPE CHASSIS-MOUNTED CAMPER DELIVERY VAN (WALK-IN)	
HIGHEST POLICE INJURY SEVERITY CODE FOR THIS VEHICLE		(34) S (35) T (36) C	STRAIGHT TRUCK FRUCK-TRACTOR (BOBTAIL) CHASSIS-CAB INKNOWN HEAVY TRUCK	
(0) O - NO INJURY (1) C - POSSIBLE INJURY (2) B - NON-INCAPACITATING INJURY (3) A - INCAPACITATING INJURY (4) K - FATAL (5) INJURED, SEVERITY UNKNOWN (6) DIED PRIOR TO ACCIDENT (7) NON-FATAL INJURY SEVERITY UNKNOWN (8) UNOCCUPIED VEHICLE (NOT APPLICABLE) (9) UNKNOWN	55	(38) T (39) T BUS (40) U (41) S (42) IN (43) T (44) S (68) T (69) L0	RACTOR & SEMI-TRAILER (SEMI) RUCK (OR SEMI) & FULL TRAILER(S) INKNOWN BUS TYPE CHOOL BUS VTERCITY BUS (BETWEEN CITIES) RANSIT BUS (INTRACITY) TREETCAR (ON TRACKS) RAIN (CARS) OCOMOTIVE (ENGINE, SWITCHER)	
ૐ		WHEELE	NKNOWN BASE <i>(cm)</i> INKNOWN	999

Duplicate columns 1-8 from the previous card.	Module O V	Format <u>0</u> _	2 OTHER	VEHICLE	OV-2
		ORIGINA	AL SPECIFICATIONS	•	
Wheelbase	999	cm	Front Overhang	999	cm
Curb Weight	9999	kg	Rear Overhang	009	cm
Average Track Width	999	cm	Undeformed End Width (UEW)	999	cm
Overall Length	999	cm	Engine Displacement	$\frac{9}{31} \cdot \frac{9}{32}$	L
Overall Width (OAW)	999	cm	Engine: # of Cylinders	$\frac{95}{33}$	

VEHICLE DAMAGE



FRONTAL CRASH OVERLAP

Round up for .5. 98 = 98% or more Enter % overlap or "99" for missing or N/A. Direct Damage Length (DDL)

 $\frac{999}{35}$ cm $\frac{99}{38}$ %

Front-End Overlap (Percent) =
$$\frac{DDL}{UEW}$$

Vehicle Overlap (Percent) = <u>DDL + 1/2 (OAW - UEW)</u> OAW

Duplicate columns 1-8 from the previous card. Module V D Format 0 9 10 11	4 VEHICLE DESCRIPTION VI	D-1
MAKE: DODGE	CARGO: _NONE	
MODEL: DAKOTA SPORT	445 regular	
	CAB Short Lox	
VIN 1 B 7 F L 2 6	X5X5 COOO	<u>م</u>
MANUFAC/BODY CODE	STOLEN VEHICLE	
MAKE/MODEL CODE 3223	(0) NO (1) YES (8) NOT COLLECTED	<u>8</u>
MODEL YEAR 1 39 9 9	(9) UNKNOWN	
VEHICLE MASS (kg) $\frac{\mathcal{O}}{43}$ $\frac{\mathcal{O}}{2}$ $\frac{\mathcal{O}}{2}$ $\frac{\mathcal{O}}{2}$	BODY STRUCTURE	2
ODOMETER (km) (ENTER 9'S IF UNKNOWN) (ENTER 8'S IF ELECTRONIC) 49	(1) BODY & FRAME (2) UNITIZED (3) INTEGRAL-STUB FRAME (4) BODY & PLATFORM FRAME	63
NUMBER OF OCCUPANTS (ENTER 9'S IF UNKNOWN)	(E.G. VW BUG) (5) PARTIALLY UNITIZED (7) OTHER: (9) UNKNOWN	
TRAVELING SPEED (km/h)	1	
(000) PARKED OR STOPPED (995) JUST STARTING UP	TRANSMISSION	
(996) BACKING UP (997) SPEED NOT EXCESSIVE (BUT UNKNOWN)	(0) NONE	
(998) SPEED EXCESSIVE (BUT UNKNOWN) (999) UNKNOWN	(1) AUTOMATIC (2) MANUAL (9) UNKNOWN	64
VEHICLE TYPE	LOCATION OF TRANSMISSION	
PASSENGER VEHICLE (11) 2-DOOR HARDTOP (NO UPPER B-PILLAR)	SELECTOR LEVER	
(12) 2-DOOR SEDAN OR COUPE 60	61 (1) FLOOR	<u>3</u>
(ANY UPPER B-PILLAR) (13) 4-DOOR HARDTOP	(2) CONSOLE - (3) COLUMN	65
(14) 4-DOOR SEDAN (15) STATION WAGON	(7) OTHER:	
(16) CONVERTIBLE (18) OTHER PASS. VEH. :	(,,	
(19) PASSENGER VEHICLE, TYPE UNKNOWN		
MULTIPURPOSE PASSENGER VEHICLE	STEERING	,
(21) SMALL UTILITY (E.G. JEEP, SCOUT, BRONCO) (22) LARGE UTILITY (E.G. PANEL TRUCK, SUBURBAN)	(1) POWER	
(23) VAN, SIZE UNKNOWN (24) VAN, SMALL (MINI)	(2) MANUAL (9) UNKNOWN	66
(25) VAN, LARGE (29) MPV, TYPE UNKNOWN		
(30) MOTOR HOME		
TRUCK . (31) PICKUP TRUCK, UNKNOWN	BRAKES	1
(32) PICKUP TRUCK, SMALL (DOWNSIZED) (33) PICKUP TRUCK, LARGE	(1) POWER	1
(99) UNKNOWN	(2) MANUAL (9) UNKNOWN	67
,		

· 基實

-		VEHICLE DESCRIPTION VD-2
TYPE OF BRAKES (1) DRUM, ALL WHEELS (2) DISC, FRONT WHEELS (3) DISC, ALL WHEELS (9) UNKNOWN	2 68	WHEELBASE (cm) (999) Unknown
BRAKE ANTI-LOCK DEVICE (0) NONE INSTALLED (1) TWO-WHEEL (2) FOUR-WHEEL (7) EQUIPPED, UNKNOWN WHEELS (9) UNKNOWN AIR CONDITIONING IN VEHICLE (0) NO (1) YES (8) NOT COLLECTED (9) UNKNOWN	8 70	PLASTIC ANTI-LACERATIVE INNER LAYER GLASS EQUIPPED (0) NONE (1) WINDSHIELD (2) WINDSHIELD AND SIDE (7) OTHER (9) UNKNOWN
TYPE OF DRIVE (1) REAR WHEEL (2) FRONT WHEEL (3) FOUR WHEEL (4) ALL WHEEL DRIVE (9) UNKNOWN DUAL REAR WHEELS (0) NO (1) YES (9) UNKNOWN ORIGINAL TYPE OF RESTRAINT SYSTEM (1) ACTIVE BELT (2) PASSIVE BELT (3) AIRBAG (4) KNEE BOLSTERS (7) OTHER: (8) NOT APPLICABLE (NOT EQUIPPED) (9) UNKNOWN EQUIPPED WITH ROLL BAR (0) NO (1) YES (9) UNKNOWN	71 0 72 73	FIELD INVESTIGATOR INSTRUCTIONS: 1. INDICATE CRUSHED AREAS BY OUTLINING NEW PERIMETER OF VEHICLE AND SHADING THE DAMAGED AREAS ON THE LARGE SKETCH ON PAGE VD-3. USE AS MANY SKETCHES AS NECESSARY TO COMPLETELY DESCRIBE THE DAMAGE. 2. ENTER THE DIMENSIONS ON THE SKETCH(ES) MEASURED TO THE POINT OF MAXIMUM PENETRATION BY THE OBJECT(S) CONTACTED. USE THE EXAMPLES BELOW AS A GUIDE. 3. ENTER THE THREE DIMENSIONS TO THE CENTER OF THE WHEELS (WHEELBASE, FRONT AND REAR OVERHANGS) ON BOTH SIDES OF THE CAR. 4. ADD OTHER DIMENSIONS AS NECESSARY TO COMPLETELY DESCRIBE THE DAMAGE. EXAMPLES:
(9) UNKNOWN TYPE OF ROOF (0) NONE (1) SOLID (2) T-TOP CLOSED (3) T-TOP OPEN (4) SUN ROOF CLOSED (5) SUN ROOF OPEN (6) CONVERTIBLE CLOSED (7) CONVERTIBLE OPEN (8) OTHER: (9) UNKNOWN	75	ROOF (REFERENCE TO TOP OF DOOR SILL OR WINDOW SILL)

Duplicate columns 1-8 from the previous card. Module V D Format 0 2 9 10 11 12

VEHICLE DESCRIPTION

VD-3

ORIGINAL SPECIFICATIONS

Wheelbase

Front Overhang

Curb Weight

2073

Rear Overhang

Average Track Width

Undeformed End Width (UEW)

Overall Length


Engine Displacement

Overall Width (OAW)

Engine: # of Cylinders

VEHICLE DAMAGE

MEASUREMENTS IN CENTIMETERS



stringline was set at 385 subtract 14 from all C's.

FRONTAL CRASH OVERLAP

Round up for .5. 98 = 98% or more Enter % overlap or "99" for missing or N/A.

Direct Damage Length (DDL)

Front-End Overlap (Percent) = DDL UEW

Vehicle Overlap (Percent) = <u>DDL + 1/2 (OAW - UEW)</u>

	A Format 0 2	DAMAGE DA-1
Primary	CASE VEHICLE PRIMARY CDC	CONTACTED VEHICLE ASSOCIATED CDC
EVENT NUMBER	1 13	veh.B
IMPACT SPEED (km/h)	9 9	999
ESTIMATED BY		<u>/</u> 38
CRUSH (cm)	<u>6_/</u>	999 39 40 41
CDC #1	11. FD EW 3	99.0000.0
CDC #2	98.0000.0	99.0000.0
from the previous card. 9 1	A Format 0 3 0 11 12 CASE VEHICLE SECONDARY CDC	CONTACTED VEHICLE ASSOCIATED CDC
SECONDARY		
EVENT NUMBER	13	
IMPACT SPEED (km/h)	14 15 16	35 36 37
ESTIMATED BY	17	38
CRUSH (cm)	18 19 20	39 40 41
CDC #1	21	42 48
CDC #2	28	49
Codes		
EVENT NUMBER	IMPACT SPEED ESTIMATOR	CRUSH
(8) NOT APPLICABL (9) UNKNOWN	(2) DRIVER (3) POLICE	(998) NOT APPLICABLE (<i>NO VEHICLE/DAMAGE</i>) (999) UNKNOWN *
IMPACT SPEED (998) NOT APPLICAE	(4) "CRASH" PROGRAM (5) OTHER COMPUTER PROGRAM BLE SPECIFY:	CDC
(999) UNKNOWN	(7) OTHER:	(9800000) NOT APPLICABLE (9900000) UNKNOWN

Module <u>D</u> <u>A</u> Format <u>0</u> <u>1</u> 12 Duplicate columns 1-8 DAMAGE DA-2 from the previous card. MAXIMUM SHEET METAL CRUSH (cm) (999) UNKNOWN 06 [**FRONT** RIGHT SIDE <u>O</u> O O REAR LEFT SIDE 000 **ROOF OTHER** CHRONOLOGICAL SEQUENCE OF DAMAGE/INJURY PRODUCING CRASH EVENTS FOR CASE VEHICLE NOTE: IF CHRONOLOGICAL ORDER DO YOU KNOW THIS TABLE TO BE IN CHRONOLOGICAL ORDER? IS UNKNOWN, EVENT ORDER IS OPTIONAL. (0) NO (1) YES EVENT NUMBER **IMPACT LOCATION IMPACT** OBJECT/VEHICLE CONTACTED CONFIGURATION (1) ON ROADWAY FOR CODES, SEE TABLE (2) SHOULDER/MEDIAN/GORE FOR CODES, SEE TABLE (3) ON ROADSIDE ON PAGE DA-3. ON PAGE DA-4. (4) OUTSIDE ROADSIDE **RIGHT-OF-WAY** (5) OTHER (6) OFF ROADWAY, LOC. UNK. (9) UNKNOWN #1 32 #2 37 #3 42 #4 47 #5 52 #6 57 #7 主 62

DAMAGE DA-3

CODES FOR IMPACT CONFIGURATION

FRONT OF CASE VEHICLE

- (11) AND FRONT OF CONTACTED VEHICLE
- (13) AND SIDE OF CONTACTED VEHICLE (14) AND REAR OF CONTACTED VEHICLE
- (16) ENDSWIPED BY CONTACTED VEHICLE
- (17) AND OBJECT
- (19) AND UNKNOWN OTHER VEHICLE CONFIGURATION

LEFT SIDE OF CASE VEHICLE

- (21) AND FRONT OF CONTACTED VEHICLE (TYPE T)
- (22) AND FRONT OF CONTACTED VEHICLE (TYPE L)
- (23) AND SIDE OF CONTACTED VEHICLE (NOT SIDESWIPE)
- (24) AND REAR OF CONTACTED VEHICLE (TYPE T)
- (25) AND REAR OF CONTACTED VEHICLE (TYPE L)
- (26) SIDESWIPED BY CONTACTED VEHICLE
- (27) AND OBJECT
- (29) AND UNKNOWN OTHER VEHICLE CONFIGURATION

REAR OF CASE VEHICLE

- (31) AND FRONT OF CONTACTED VEHICLE
- (33) AND SIDE OF CONTACTED VEHICLE
- (34) AND REAR OF CONTACTED VEHICLE
- (36) ENDSWIPED BY CONTACTED VEHICLE
- (37) AND OBJECT
- (39) AND UNKNOWN OTHER VEHICLE CONFIGURATION

RIGHT SIDE OF CASE VEHICLE

- (41) AND FRONT OF CONTACTED VEHICLE (TYPE T)
- (42) AND FRONT OF CONTACTED VEHICLE (TYPE L)
- (43) AND SIDE OF CONTACTED VEHICLE (NOT SIDESWIPE)
- (44) AND REAR OF CONTACTED VEHICLE (TYPE T)
- (45) AND REAR OF CONTACTED VEHICLE (TYPE L)
- (46) SIDESWIPED BY CONTACTED VEHICLE (47) AND OBJECT
- (49) AND UNKNOWN OTHER VEHICLE CONFIGURATION

OTHER

- (57) VEHICLE TO OBJECT
- (58) VEHICLE TO VEHICLE
- (59) VEHICLE TO VEHICLE, CONFIGURATION UNKNOWN

ROLLOVER

- (61) LESS THAN 360°
- (62) 360° OR MORE
- (69) DETAILS UNKNOWN

UNKNOWN

(99) IMPACT TYPE UNKNOWN

DAMAGE DA-4

CODES FOR VEHICLE/OBJECT CONTACTED

VEHICLE/OBJECT GROUPS BUS NO OBJECT (00)(40) UNKNOWN BUS TYPE (01) - (39) PASSENGER VEHICLE & TRUCK (41) SCHOOL BUS (40) - (69) OTHER VEHICLE (42) INTERCITY BUS (BETWEEN CITIES) (70) - (76) PEDESTRIAN & ON-ROADWAY OBJECT (43) TRANSIT BUS (INTRACITY) (77) - (97) OFF-ROADWAY OBJECT (44) STREETCAR (ON TRACKS) OTHER (DESCRIBE) (99) UNKNOWN MOTORCYCLE (50) UNKNOWN MOTORCYCLE TYPE **PASSENGER VEHICLE** (51) 1 - 75 cc (52) 76 - 125 cc (53) 126 - 250 cc (02) LARGE (03) LIMOUSINE (17) PICKUP (54) 251 - 500 cc (20) UNKNOWN PASSENGER VEHICLE BODY (55) 501 - 750 cc (24) SUB-MINI (56) 751 cc + (25) MINI (57) 3-WHEELS (OR WITH SIDECAR) (26) SUB-COMPACT (27) COMPACT SPECIAL PURPOSE VEHICLE (60) UNKNOWN/OTHER SPECIAL VEHICLE (DESCRIBE) (28) INTERMEDIATE (29) FULL (61) SNOWMOBILE (62) ATV (ALL TERRAIN VEHICLE) (63) AMPHIBIOUS VEHICLE SIZE WHEELBASE (64) FARM VEHICLE (65) CONSTRUCTION VEHICLE SUB-MINI < 2286 mm (< 90") (66) TRAILER, PRIVATE (CAMPER) MINI 2286 - 2412 mm (90° - 94.9°) (67) TRAILER, COMMERCIAL (CARGO) SUB-COMPACT (68) TRAIN (CARS) 2413 - 2539 mm (95" - 99.9") COMPACT 2540 - 2666 mm (100" - 104.9") (69) LOCOMOTIVE (ENGINE, SWITCHER) INTERMEDIATE 2667 - 2793 mm (105" - 109.9") FULL 2794 - 2920 mm (110" - 114.9") 2921 - 3174 mm (115" - 124.9") LARGE **OBJECT** LIMOUSINE > 3175 mm (> 125") (70) PEDESTRIAN (71) BICYCLIST, OTHER PEDALCYCLIST (72) PEDESTRIAN CONVEYANCE (E.G. PERSON RIDING MULTIPURPOSE PASSENGER VEHICLE ANIMAL, CART) (11) SMALL VAN (MINI) (73) LARGE ANIMAL (12) PICKUP (74) FALLEN OBJECT (E.G. OBJECT DISLODGED FROM (14) SMALL UTILITY (WHEELBASE LESS THAN 107", OTHER VEHICLE, FALLEN TREE, ROCKS) E.G. JEEP, BRONCO) (75) ROCKS (15) LARGE UTILITY (WHEELBASE MORE THAN 107", (76) CONSTRUCTION EQUIPMENT (EXCLUDING (65)) E.G. PANEL TRUCK, SUBURBAN) (77) SIGN POST, UTILITY POLE, TREE (16) PICKUP TRUCK WITH CANOPY/SHELL COVER (17) PICKUP CAR WITH CANOPY/SHELL COVER (78) DITCH (79) EMBANKMENT, SNOWBANK, RR TRACKS RR X (21) MOTOR HOME (80) GROUND (ROLLOVER ONLY) (81) CURB (DAMAGE PRODUCING IMPACTS ONLY) (22) PICKUP TRUCK WITH SLIDE-IN CAMPER (23) PICKUP CAR WITH SLIDE-IN CAMPER (82) CULVERT (31) CHASSIS-MOUNTED CAMPER (83) FENCE (84) HYDRANT, SHORT POST, STUMP (85) SMALL POST/TREE, RURAL MAIL BOX, MILE TRUCK MARKER, DELINEATOR (11) SMALL VAN (E.G. ECONOLINE) (86) BUILDING (12) PICKUP TRUCK (87) PIER, PILLAR, BRIDGE SUPPORT (13) UNKNOWN LIGHT TRUCK (88) ABUTMENT, RETAINING WALL (15) LARGE UTILITY (E.G. PANEL TRUCK, SUBURBAN) (89) BRIDGE RAIL (16) PICKUP TRUCK WITH CANOPY/SHELL COVER (90) GUARD RAIL, LEADING SECTION (22) PICKUP TRUCK WITH SLIDE-IN CAMPER (91) GUARD RAIL, MIDDLE OR UNKNOWN (92) GUARD RAIL, TRAILING SECTION (30) UNKNOWN TRUCK TYPE (31) CHASSIS-MOUNTED CAMPER (93) GUARD POST (TIMBER, METAL, CONCRETE) (94) CABLE, FENCE BARRIER (33) DELIVERY VAN (WALK-IN) (34) STRAIGHT TRUCK (95) CONCRETE BARRIER (MEDIAN) (35) TRUCK-TRACTOR (BOBTAIL) (96) IMPACT ATTENUATOR (36) CHASSIS-CAB (97) BREAKAWAY FEATURES (37) UNKNOWN HEAVY TRUCK

主.

(38) TRACTOR & SEMI-TRAILER (SEMI) (39) TRUCK (OR SEMI) & FULL TRAILER(S)

- -

				BEST AVAILABLE
	R Format 0 1 12		H RECONSTRUC	TION CR-1
	CASE VEHICLE F	PRIMARY IMPACT	CASE VEHICLE SE	CONDARY IMPACT
	CASE VEHICLE	CONTACTED VEHICLE	CASE VEHICLE	CONTACTED VEHICLE
EVENT NUMBER	13		47	
ΔV (km/h) TOTAL	0 3 4	8 - 32 33 34	48 49 50	66 67 68
LONGITUDINAL*	$\frac{-0}{17}$ $\frac{3}{20}$	$\frac{8}{35}$ ${}$ ${}$ ${}$ ${}$ ${}$ ${}$ ${}$ ${}$ ${}$	51 54	69 72
LATERAL*	+006	8		
*NOTE: THESE ΔV COMPONENTS MUST INCLUDE SIGN.	21 24	39 42	55 58	73 76
EXAMPLES: 10 km/h = ± <u>0</u> 1 <u>0</u> -7 km/h = <u>:</u> <u>0</u> <u>0</u> Z				
ENERGY DISSIPATED BY CRUSH (kg)	<u>O</u> 103	<u>8</u>	59 62	77 — <u>80</u>
RECONSTRUCTION				
(01) RECONSTRUCTED, UNKNOWN CONFIDENCE LEVEL	22			
(21) RECONSTRUCTED, LOW CONFIDENCE LEVEL (22) RECONSTRUCTED, MODERATE CONFIDENCE LEVEL (23) RECONSTRUCTED, HIGH CONFIDENCE LEVEL	29 30		63 64	
NOT RECONSTRUCTED BECAUSE				
(02) INSUFFICIENT DATA (03) EXCESSIVE UNDERRIDE/ OVERRIDE (04) ROLLOVER (05) VAULTING (06) OTHER TRAVEL IN MORE THAN ONE PLANE (07) NON-HORIZONTAL FORCE (08) SIDESWIPE-TYPE DAMAGE (09) YIELDING OBJECT (10) OTHER: (11) AT LEAST ONE VEHICLE BEYOND SCOPE (12) OTHER VEHICLE NOT INSPECTED		-		
MODE				
(1) CDC ONLY (2) CDC & DETAILED DAMAGE (3) TRAJECTORY & CDC (4) JRAJECTORY & CDC & DETAILED DAMAGE (5) NOT RECONSTRUCTED	31		65	-
COMPUTER PROGRAM SPECIFY: WIN SMM				

	R Format 0 2 0 11 12		H RECONSTRUCTEBS	TION CR-2	
	CASE VEHICLE F	PRIMARY IMPACT	CASE VEHICLE SECONDARY IMPACT		
	CASE VEHICLE	CONTACTED VEHICLE	CASE VEHICLE	CONTACTED VEHICLE	
EVENT NUMBER	13		47		
EBS (km/h) TOTAL	<u>O3</u> 4/	32 33 34	48 49 50	66 67 68	
LONGITUDINAL*	<u>-034</u>	35 38	51 54	69 72	
LATERAL*	+006	8		73 - 76	
*NOTE: THESE EBS COMPONENTS MUST INCLUDE SIGN.	21 24	39 42	55 58	73 76	
EXAMPLES: $10 \text{ km/h} = \pm 0.10$ -7 km/h = ± 0.07					
ENERGY DISSIPATED BY CRUSH (kg)	0 103	8 - 46	59 62	77 - 80	
RECONSTRUCTION			·		
(01) RECONSTRUCTED, UNKNOWN CONFIDENCE LEVEL	22				
(21) RECONSTRUCTED, LOW CONFIDENCE LEVEL (22)_RECONSTRUCTED, MODERATE CONFIDENCE LEVEL (23) RECONSTRUCTED, HIGH CONFIDENCE LEVEL	29 30		63 64		
NOT RECONSTRUCTED BECAUSE					
(02) INSUFFICIENT DATA (03) EXCESSIVE UNDERRIDE/ OVERRIDE (04) ROLLOVER (05) VAULTING (06) OTHER TRAVEL IN MORE THAN ONE PLANE (07) NON-HORIZONTAL FORCE (08) SIDESWIPE-TYPE DAMAGE (09) YIELDING OBJECT (10) OTHER: (11) AT LEAST ONE VEHICLE BEYOND SCOPE (12) OTHER VEHICLE NOT INSPECTED		-	-	·	
MODE					
(1) CDC ONLY (2) CDC & DETAILED DAMAGE (3) TRAJECTORY & CDC (4) TRAJECTORY & CDC & DETAILED DAMAGE (5) NOT RECONSTRUCTED	<u>2</u> 31	, - -	65	•	
COMPUTER PROGRAM SPECIFY: WIN SMAPL			·)÷		

BEST AVAILABLE CRASH RECONSTRUCTION **Duplicate columns 1-8** Module <u>C</u> <u>R</u> Format <u>0</u> <u>3</u> 10 11 12 CR-3 from the previous card. 1. ENTER CRASH RECONSTRUCTION DAMAGE MEASUREMENTS IN CENTIMETERS. NOTES: CASE VEHICLE 2. MEASURE C_1 TO C_6 FROM DRIVER TO PASSENGER SIDE IN FRONT OR REAR IMPACTS, REAR TO FRONT IN SIDE IMPACTS. LOCATOR 3. D IS POSITIVE IF MEASURED TO A POINT FORWARD OF OR TO THE RIGHT OF THE CG. 4. USE THE CENTER OF THE WHEELBASE AS THE CG. Locate the end of the damage with respect to the vehicle longitudinal center line, or an undamaged axle for side impacts. Specific Impact No. Location of Direct Damage Location of Field L BC TO <u>ک</u> ر MAK Crush is C3 STRINGLIME WAS SET C6 385 From REAR WHEEL C5 BECAUJE C6 WAS OUTWARD . SHOULD BE DL 371. - 14 From all ch UDL PLANE: C2 (1) Bumper (2) Above Bumper C₁ (3) Sill (4) Above Sill (5) Other (9) Unknown **CRUSH PROFILE IN CENTIMETERS** NOTE: Each line in the table below is a separate record (card) Duplicate columns 1 - 12 for each completed line. Specific **Direct Damage** Plane of Impact Impact Length Max Field C_3 C₁ C_2 C₄ C_5 ±D C_{6} Number C-Measur. (DDL) Crush 162 75 44 STRINGING ACCOUNTMENT 14 -14 -14 FREESOACE 0 0 5 61 205 TOTA 61 30 0 1 162 021 033 061 030 001 000 1000 13 15 16 17 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 3 2

										BEST	AVAILABLE
Duplicate from the	e columns 1-8 previous card.	Module <u>C</u>	R Forma	at <u>0 4</u>		C	RASH F	RECON	STRUCT	TION	CR-4
NOTES	2. MEASU IMPAC 3. D IS PO	R CRASH RECO URE C ₁ TO C ₆ I TS, REAR TO FI OSITIVE IF MEA HE CENTER OF	FROM DRIVER RONT IN SIDE ISURED TO A I	TO PASSENCIMPACTS. POINT FORW. PASE AS THE	GER SIDE IN ARD OF OR CG.	I FRONT O	R REAR IGHT OF TH		L	ER VEH	
	Impact No.		Location of			er line, or	an unuam		ion of Fi		
			-								
PLAI	(1) Bumper (2) Above Burr (3) Sill (4) Above Sill (5) Other (9) Unknown		CRUSH- ole below is a	C6 C5 C4 C3 C2 C1	E IN CEI			DL UDL		a complete	d line.
Specific Impact Number	Plane of Impact C-Measur.	Direct Length (DDL)	Damage Max Crush	Field	C ₁	C ₂	C ₃	C ₄	C ₅	c ₆	±D
-					-	_					
13	14	44 9 15 16 17	999	999 21 22 23	999 24 25 26	999 27 28 29	999 30 31 32	999 33 34 35	999 36 37 38	999 39 40 41	9999
3 -	> -									-	

Duplicate columns 1-8 Module W T from the previous card. 9 10	Format 0	1 12	WHEELS AND TIRES WT-1
WHEELSDAMAGED (0) NO (1) YES (9) UNKNOWN	LF RF RR LR	O 13 1 O 0	SIZE (NOT DOT CODE. IF UNKNOWN, USE 9'S) LF
TIRE TREAD TYPE (1) REGULAR (2) SNOW (3) SLICKS (4) ALL WEATHER (MS) (7) OTHER: (9) UNKNOWN	LF RF RR LR	¥	LR
CARCASS CONSTRUCTION (1) BIAS (2) BELTED BIAS (3) RADIAL (4) ELLIPTICAL (5) HI PRESSURE SPARE (6) SPACE SAVER SPARE (7) OTHER: (9) UNKNOWN	LF RF RR LR	3 3 3 3 x	
IF VEHICLE IS EQUIPPED WITH DUAL WHEELS, COMPLETE FOR OUTER WHEELS AND MAKE NOTES ON INNER WHEELS. NOTES:			

		BES	ST AVAILABLE
Duplicate columns 1-8 from the previous card. Module F T Format 0 9 10 11	1 12	FUEL AND FUEL TANKS	FT-1
TYPE OF PROPULSIVE FUEL (1) GASOLINE (2) DIESEL OIL (3) LPG (4) ELECTRIC (7) OTHER: (9) UNKNOWN	13	AUXILIARY TANK TYPE (1) OEM TANK (2) AFTER MARKET TANK (8) NOT APPLICABLE (NOT EQUIPPED) (9) UNKNOWN	21
MAIN TANK LOCATION	<u>322</u>	AUXILIARY TANK LOCATION	<u>888</u>
MAIN FILLER CAP LOCATION	1 13	AUXILIARY FILLER CAP LOCATION	888
MAIN TANK MATERIAL C	9 20	AUXILIARY TANK MATERIAL	28
TANK AND F		AP LOCATION CODES	
(2) IN K (3) BET (4) FOF	WEEN KIC WARD OF APPLICAE	K-UP & COWL	
SECOND DI	IGIT <i>(LATEI</i>	RAL)	
(2) WIT (3) RIG (4) DUA	HT OF FRA NL, RIGHT 8 APPLICAE	OR CENTERED	
THIRD DIGI	T (VERTICA	AL)	

- (1) BELOW FRAME
 (2) WITHIN FRAME OR CENTERED
 (3) ABOVE FRAME
 (8) NOT APPLICABLE (NOT EQUIPPED)
 (9) UNKNOWN

TANK MATERIAL CODES

- (1) STEEL
 (2) ALUMINUM
 (3) PLASTIC
 (7) OTHER
 (8) NOT APPLICABLE (NOT EQUIPPED)
 (9) UNKNOWN

Duplicate columns 1-8 from the previous card.

FUEL LEAKAGE

FL-1

DID FUEL LEAKAGE RESULT FROM A CRASH EVENT

(0) NO KNOWN LEAKAGE SKIP PAGE.

(1) YES COMPLETE PAGE.



	1	11	111	IV	V	
LEAK NUMBER	LEAKING COMPONENT	COMPONENT SOURCE	TYPE OF DAMAGE	SEVERITY OF DAMAGE	LOCATION OF LEAK	EVENT NUMBER
#1	14 15	<u>-</u>		_		21
#2	22 23			_		29
#3	30 31					37
#4	38 39					45
#5	46 47					53

I LEAKING COMPONENT

TANK AREA

- (11) MAIN FUEL TANK (INCLUDING VAPOR RECOVERY DOME)
- (12) AUXILIARY FUEL TANK
- (13) MAIN TANK FILLER TUBE
- (14) MAIN TANK CAP (GAS CAP)
- (15) AUXILIARY TANK FILLER TUBE
- (16) AUXILIARY TANK CAP (GAS CAP)
- (19) TANK AREA, DETAILS UNKNOWN

DELIVERY SYSTEM

- (21) FUEL FEED LINE (MAIN TANK TO FUEL PUMP)
- (22) FUEL FEED LINE (AUXILIARY TANK TO FUEL PUMP)
- (23) FUEL RETURN LINE (FUEL PUMP TO TANK)
- (24) INLINE FUEL FILTER
- (25) FUEL LINE (PUMP TO
 - CARBURETOR OR INJECTOR PUMP)
- (26) CARBURETOR TO INJECTOR PUMP
- (27) FUEL PUMP
- (29) DELIVERY SYSTEM, DETAILS UNKNOWN

EVAPORATIVE EMISSION CONTROL SYSTEM

- (31) ATMOSPHERIC VENT PIPE (NON-EEC EQUIPPED)
- (32) EEC PIPE (VAPOR CANISTER TO CARBURETOR)

EEC SYSTEM (CONTINUED)

- (33) VAPOR RECOVERY HOSES (CANISTER TO CARBURETOR)
- (34) LIQUID-VAPOR SEPARATOR (UNLESS PART OF TANK)
- (35) CANISTER
- (39) EEC SYSTEM, DETAILS UNKNOWN
- (49) ENGINE COMPARTMENT, COMPONENT UNKNOWN
- (99) COMPONENT UNKNOWN

II COMPONENT SOURCE

- (1) OEM
- (2) AFTER MARKET
- (9) UNKNOWN

III TYPE OF DAMAGE

- (1) DENTED/CRUSHED
- (2) PUNCTURED
- (3) RUPTURED
- (4) SEVERED/GROSS TEARS
- (5) DISCONNECTED/DEFEATED
- (9) UNKNOWN

IV SEVERITY OF DAMAGE

- (1) MINOR
- (2) MODERATE
- (3) SEVERE
- (4) DISCONNECTED/DEFEATED
- (9) UNKNOWN

V LOCATION OF LEAK

FIRST DIGIT (LONGITUDINAL LOCATION)

- (1) F, FORWARD OF COWL
- (2) P, BETWEEN COWL & REAR BULKHEAD
- (3) B, BEHIND REAR BULKHEAD
- (4) Y, F, & P
- (5) Z, P, & B
- (6) D. DISTRIBUTED (F, P & B)
- (9) UNKNOWN

SECOND DIGIT (LATERAL LOCATION)

- (1) L, LEFT
- (2) C, CENTER
- (3) R, RIGHT
- (4) Y, LEFT CENTER (L & C)
- (5) Z, RIGHT CENTER (R & C)
- (6) D, DISTRIBUTED (F, P & B)
- (9) UNKNOWN

Duplicate columns 1-8 Module F R Format 0 from the previous card.		FIRE	FR-1
WAS THERE FIRE IN (0) NO <u>SKIP</u> PAC (1) YES <u>COMPLE</u>	GE.	CASE VEHICLE?	
DID FIRE START IN CASE VEHICLE? (0) NO (1) YES (9) UNKNOWN	14	SEVERITY OF FIRE DAMAGE (1) MINOR (2) MODERATE (3) SEVERE (9) UNKNOWN	16
FLAME PROPOGATION RATE (1) RAPID/EXPLOSIVE (2) SLOW/MODERATE (9) UNKNOWN	15	DID AN INJURY TO CASE VEHICLE OCCUPANT RESULT FROM FIRE IN OR ON CASE VEHICLE? (0) NO (1) YES (9) UNKNOWN	17

PROVIDE NOTES IF FIRE OCCURRED.

Duplicate columns 1-8 Module E D from the previous card. 9 10	Format <u>0</u> <u>1</u>	EXTERIOR DAMAGE	ED-1
	EASED O	STEERING COL FLEXIBLE COUPLING FLEXIBLE COUPLING TYPE (0) NONE (1) FLEXIBLE MATERIAL (2) POT (3) SINGLE U-JOINT (4) DOUBLE U-JOINT (5) FLEXIBLE CABLE (6) COMBINATION OF ABOVE (CIRCLE EACH) (7) OTHER: (8) EQUIPPED, TYPE UNKNOWN (9) UNKNOWN, IF EQUIPPED COUPLING- -DAMAGED	9 26
-JAMM HOOD HINGESLEFT, DAMA	15	(USE CODES FROM <u>HOOD</u> <u>PERFORMANCE</u>) -SEPARATED (COMPLETE)	9 28
(COM) -RIGHT, DAMA -RIGHT, SEPAF	RATED PLETE) RATED 18 RATED 19	ENG COMPART TELESCOPING UNIT TYPE OF UNIT (00) NONE INSTALLED (01) - (07) SEE UNITS ON PAGE ED-2 (88) NOT COLLECTED	<u>8</u> <u>8</u> 29 30
HOOD REMAINED ON VEHICLE REAR EDGE OF HOODELEVA -CONTACTED WINDSH	7.	(97) OTHER:	
-PENETRATED WINDSH HOOD LATCH LOCATION (1) FRONT OF VEHICLE (2) COWL AREA (3) SIDE (8) NOT APPLICABLE (9) UNKNOWN	HIELD 23	TELESCOPED LENGTH (mm) G: DIFFERENCE (mm) F (OR H) - G (IF LESS THAN 15mm, ENTER *000*.)	
ENGINE OR TRANSMISSION MOUNT SEPARATION (COMPLETE) (0) NO (1) YES (9) UNKNOWN	T	(888) NOT COLLECTED (991) NOT MEASURED/NO COMPRESSION (992) COMPRESSED, AMOUNT UNKNOWN (993) DEVICE EXTENDED (997) UNABLE TO BE MEASURED (998) NOT APPLICABLE (NOT EQUIPPED) (999) UNKNOWN	8 8 8

-		Exterior Damage	ED-2
LEFT-SIDE BODY MOUNT DID BODY MOUNT SEPARATE? (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	8	LEFT DOORS HOW DID DOORS OPEN DURING COLLISION?	
LEFT PILLARS PILLARS SEPARATED COMPLETELY - USE CODES: (0) NO (1) YES (4) NO SEPARATION, BUT DAMAGED (8) NOT APPLICABLE (NOT EQUIPPED) (9) UNKNOWN		USE CODES: (0) DOOR DID NOT OPEN OPENED BECAUSE OF (1) HINGE AREA SEPARATION (2) DOOR-LATCH SEPARATION (3) LATCH-STRIKER SEPARATION (4) STRIKER-PILLAR SEPARATION (5) BODY DISTORTION (6) COMBINATION OF ABOVE (CIRCLE EACH) (7) OPENED, REASON UNKNOWN	
-A-PILLAR, UPPER	<u>⊘</u> 35	(8) NOT APPLICABLE <i>(NO DOOR)</i> (9) UNKNOWN	a
LOWER	<u>36</u>	-FRONT -REAR	اء (لماء
-B-PILLAR, UPPER	<u>O</u> 37		**
- LOWER	<u>Ø</u> ₃8	DOORS JAMMED CLOSED- USE CODES: (0) NO (1) YES	
-C-PILLAR, UPPER	₹	(8) NOT APPLICABLE <i>(NO DOOR)</i> (9) UNKNOWN	
LOWER	40	-FRONT -REAR) 4 (6)
-D-PILLAR, UPPER	\$		46
LOWER	42		
≱ _ ₃:			

		550	T AVAILABL
		EXTERIOR DAMAGE	ED-3
Rear Door		OTHER REAR DAMAGE	
REAR DOOR TYPE		WAS PARTITION TO LUGGAGE AREA DAMAGED DURING COLLISION? (0) NO	2
(0) NO DOOR (INCLUDES PICKUPS) (1) HATCHBACK (2) ONE-WAY TAILGATE (3) TWO-WAY TAILGATE (4) CLAMSHELL/DISAPPEARING	47	(1) YES (8) NOT APPLICABLE (9) UNKNOWN	50
TAILGATE (5) SINGLE DOOR (6) DOUBLE DOOR (9) UNKNOWN		SPARE TIRE (0) NO SPARE TIRE (1) NOT ATTACHED BEFORE COLLISION	8
Hatchback		(2) ATTACHED BEFORE COLLISION (2) ATTACHED, NOT SEPARATED IN COLLISION (3) ATTACHED BEFORE COLLISION (6) NOT COLLISION (8) NOT COLLECTED	51
One-way		(9) UNKNOWN	
Two-way or or		TRAILER HITCH TYPE (0) NO HITCH	8
Clamshell		BALL-AND-SOCKET TYPES	52
Single door		 (1) TEMPORARY FRAMEWORK (E.G. RENTAL CLAMP-ON) (2) BUMPER-MOUNT ONLY (E.G. LIGHT TRUCK) (3) BUMPER-AND-FRAME (BUT NON- 	
Double door		EQUALIZING) (4) LOAD EQUALIZING OTHER TYPES	
HOW DID DOOR OPEN DURING COLLISION?		(5) RING-AND-PINTLE(6) FIFTH-WHEEL (INCL. P/U)(7) OTHER (E.G. CLEVIS-AND-PIN)	
(0) DOOR DID NOT OPEN OPENED BECAUSE OF	<u>\$</u>	(8) EQUIPPED, TYPE UNKNOWN (9) UNKNOWN IF EQUIPPED	
(1) HINGE AREA SEPARATION (2) DOOR-LATCH SEPARATION (3) LATCH-STRIKER SEPARATION (4) STRIKER-PILLAR SEPARATION (5) BODY DISTORTION		TRAILER TYPE (AT TIME OF COLLISION)	<u>~</u>
(6) COMBINATION OF ABOVE (CIRCLE EACH) (7) OPENED, REASON UNKNOWN		(0) NO TRAILER (1) TRAVEL-TRAILER/CAMPER (2) MOBILE HOME (3) BOAT/SNOWMOBILE/ATV TRAILER	53
(8) NOT APPLICABLE (NO DOOR) (9) UNKNOWN		(4) UTILITY TRAILER (5) TOWED CAR (7) OTHER: (8) TRAILER, TYPE UNKNOWN	
DOOR JAMMED CLOSED	0	(9) UNKNOWN	
(1) YES (8) NOT APPLICABLE (NO DOOR) (9) UNKNOWN	49		

-		EXTERIOR DAMAGE	ED-4
RIGHT-SIDE BODY MOUNT DID BODY MOUNT SEPARATE? (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	54	RIGHT DOORS HOW DID DOORS OPEN DURING COLLISION? USE CODES:	-
RIGHT PILLARS PILLARS SEPARATED COMPLETELY - USE CODES: (0) NO (1) YES (4) NO SEPARATION, BUT DAMAGED (8) NOT APPLICABLE (NOT EQUIPPED) (9) UNKNOWN		(00) DOOR DID NOT OPEN OPENED BECAUSE OF (01) HINGE AREA SEPARATION (02) DOOR-LATCH SEPARATION (03) LATCH-STRIKER SEPARATION (04) STRIKER-PILLAR SEPARATION (05) BODY DISTORTION (06) COMBINATION OF ABOVE (CIRCLE EACH) (07) OPENED, REASON UNKNOWN (11) VAN RIGHT-REAR DOOR OPENED (ANY MECHANISM)	
-A-PILLAR, UPPER	<u>O</u> 55	(98) NOT APPLICABLE <i>(NO DOOR)</i> (99) UNKNOWN -FRONT	<u>36</u>
LOWER -B-PILLAR, UPPER	<u>\$</u>	-REAR	63 64 98 65 66
- LOWER	57	DOORS JAMMED CLOSED- USE CODES: (0) NO	9
-C-PILLAR, UPPER	8	(1) YES (8) NOT APPLICABLE <i>(NO DOOR)</i> (9) UNKNOWN	G
LOWER	<u>eo</u>	-FRONT -REAR	67
-D-PILLAR, UPPER	<u></u> €		68
LOWER	62	VAN REAR DOOR TYPE (0) VAN, NO REAR DOOR (1) TRACK (SLIDING) - RIGHT SIDE (2) SINGLE-HINGED - RIGHT SIDE (3) DOUBLE-HINGED - RIGHT & LEFT SIDE (4) TRACK (SLIDING) - RIGHT & LEFT SIDE (5) SINGLE-HINGED - RIGHT & LEFT SIDE (6) DOUBLE-HINGED - RIGHT & LEFT-SIDE (7) TRACK AND HINGED COMBINATION (8) NOT APPLICABLE (NOT A VAN) (9) UNKNOWN	69

		Exterior Damage	ED-5
WINDSHIELD DAMAGE		WINDSHIELD MARK ON CASE VEHICLE	:
WINDSHIELD CRACKED (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	70		
WINDSHIELD BROKEN (PLASTIC INTERLAYER TORN) (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	<u>8</u>	,	
CRACKED OR BROKEN BY OCCUPANT CONTACT (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN EXTENT OF BOND SEPARATION	8 72	WINDSHIELD CODE (97) DESCRIBED BUT NOT CODED (98) NOT APPLICABLE (NO WINDSHIELD) (99) UNKNOWN	9 74 75
(0) NONE (1) 1 - 20% (2) 21 - 40 (3) 41 - 60 (4) 61 - 80 (5) 81 - 99 (6) TOTAL (7) SEPARATED, AMOUNT - UNKNOWN (8) NOT APPLICABLE (9) UNKNOWN	73	ROOF DID T-ROOF/SUN ROOF OPEN DURING COLLISION? (0) NO (1) YES (8) NOT APPLICABLE (NOT A T-ROOF OR SUN ROOF) (9) UNKNOWN	8 76
- A HOMEONYAL) ON THIS DIAGRAM	REST OF THE	R DAMAGE WITH DIMENSIONS (VERTICAL WINDSHIELD AS VIEWED FROM INSIDE.	
3 - →			
<u> </u>	-		R

Duplicate columns 1-8 Module S C Format (from the previous card.	<u>1</u> 1 12	STEERING WHEEL AND COLUMN	SC-1
STEERING WHEEL		STEERING WHEEL POSITION AT TIME OF COLLISION	
STEERING WHEEL RIM DAMAGE (0) NONE (1) DEFORMED SLIGHTLY (2) SEVERELY BENT (3) BROKEN (9) UNKNOWN half	13	IN WHAT O'CLOCK POSITION WAS THE NORMAL TOP OF THE WHEEL POINTED WHEN THE COLLISION OCCURRED? EXAMPLES O'CLOCK = 1 2 O'CLOCK = 0 2	
NUMBER OF STEERING WHEEL SPOKES (9) UNKNOWN	14	(NORMAL STRAIGHT AHEAD) O'CLOCK - 99 (99) UNKNOWN	
STEERING WHL SPOKE DAMAGE (0) NONE (1) DEFORMED SLIGHTLY (2) SEVERELY BENT (3) BROKEN (9) UNKNOWN	15	STEERING WHEEL ENERGY ABSORBING DEVICE (1) EXAMPLES: BARRACUDA, 70 - 74 CHALLENGER, 70 - 74 CAPRI, 71 - 77	
STEERING COLUMN OPTIONS		- (2) EXAMPLES: OMNI, 78 - HORIZON, 78 -	
TILT FEATURE (0) NOT EQUIPPED (1) YES, EQUIPPED, UNK POSITION (2) UP (3) MIDDLE (4) LOWER (9) UNKNOWN IF EQUIPPED	16	TYPE OF DEVICE (0) NONE (1) CONVOLUTED OR MESH CYLINDER (2) DEEP DISH STEERING WHEEL (7) OTHER: (8) NOT COLLECTED (9) UNKNOWN IF EQUIPPED	8 19
SWING-AWAY FEATURE (0) NOT EQUIPPED (1) YES, EQUIPPED (9) UNKNOWN IF EQUIPPED	<u>O</u>	ORIGINAL DIMENSION (mm) A: DAMAGE DIMENSION (mm) B: DIFFERENCE (mm)	
TELESCOPING FEATURE (0) NOT EQUIPPED (1) YES, EQUIPPED (9) UNKNOWN IF EQUIPPED	18	A - B (888) NOT COLLECTED (991) NOT MEASURED/NO APPARENT COMPRESSION (992) COMPRESSED, AMOUNT UNKNOWN (993) DEVICE EXTENDED (997) UNABLE TO MEASURE (998) NOT APPLICABLE (NOT EQUIPPED) (999) UNKNOWN	8 8 8 22

<u> </u>			
		STEERING WHEEL AND COLUMN	SC-2
STEERING COLUMN		STEERING WHEEL (CONTINUED)	T
Energy Absorbing Device			
TYPE OF DEVICE * (IF 27 OR 28)		STEERING WHEEL HUB DAMAGE	
(00) NOT EQUIPPED (88) NOT COLLECTED (99) UNKNOWN	8 8 24	(0) NONE (1) OCCUPANT CONTACT (2) AIRBAG	$\frac{\circ}{33}$
ORIGINAL LENGTH (mm)		(3) OTHER (9) UNKNOWN	
C:			
COMPRESSED LENGTH (mm)			
D:		·	
BRACKET DEFLECTION (IF CODE 36, 48, OR 49 ABOVE)			
COMPRESSION (OR EXTRUSION) (mm)		16	
C - D (OR E) (TOLERANCE: ±10)			
(888) NOT COLLECTED (991) NOT MEASURED/NO APPARENT COMPRESSION (992) COMPRESSED, AMOUNT UNKNOWN (993) DEVICE EXTENDED (997) UNABLE TO BE MEASURED (998) NOT APPLICABLE (NOT EQUIPPED) (999) UNKNOWN	8 8 8 27		
* (ADD A & B FOR TOTAL COMPRESSION)	İ		
SHEAR CAPSULE SEPARATION (mm)			
S (USE AVG. OF LEFT & RIGHT CAPSULES.)			
LT:			-
RT:			
(888) NOT COLLECTED (991) NOT MEASURED/NO APPARENT SEPARATION (992) SEPARATED, AMOUNT UNKNOWN (997) UNABLE TO BE MEASURED (998) NOT APPLICABLE (NOT EQUIPPED) (999) UNKNOWN	8 8 8	-	
COLUMN VERTICAL ROTATION (0) NO APPARENT ROTATION (1) UPWARD APPARENT ROTATION (2) DOWNWARD APPARENT ROTATION (9) UNKNOWN	7 31		
CQLUMN LATERAL ROTATION (0) NO APPARENT ROTATION (1) LEFT APPARENT ROTATION (2) RIGHT APPARENT ROTATION (9) UNKNOWN	<u></u>	· • -	


	•		
·			
•			
· ~ Iv	*		
. 3 · ·			

INI	TQ1	101	ON	IT-1
111		101	L JIV	

	1						THUSION II-I
		(All Measurements Are in Centimeters)					Dominant
Location of		Comparison	_	Intruded	=		Crush
Intrusion	Intruded Component	Value		Value		Intrusion	Direction
11	Floor				_ =	6	up
					=		
			_		=		
			_		=		
			_		=		
			_		=		
			_		=		
			_		=		3.00
-			_		=		
			_		=		
			_		=		
			_				
			_				

OCCUPANT CONTACT WORKSHEET

ł					
-	Interior	Occupant	Body		Confidence
	Component	No. if	1		Level of
	· ·		Region		Contact
Contact	Contacted	Known	if Known	Supporting Physical Evidence	Point
A	Upper IP	1	Hand	Skin	2
В	Mid IP	1	Hand	Damage to panel	2
T.C	Knee bolster	1	Knee	- Scuff	1
	Parking	1	Knee/leg	Damage	1
D	brake			_	
	release				
E	Foot	1	Feet	Gas and brake pedal bent to left	1
controls				,	-
F	Sunvisor	1	Head	Bent, scuff, blood	1
G	_			,	· · ·
Н					
₹ ₂	: '			-	



INTRUSION IT-3

CODES FOR COLUMN B, OCCUPANT SPACE NUMBER

OCCUPANT SPACE NUMBER IS A TWO-DIGIT CODE. THE USE OF THE CODE IS DETERMINED BY THE VEHICLE SEAT CONFIGURATION AT THE TIME OF THE ACCIDENT.

FIRST DIGIT

THE FIRST DIGIT (LEFT DIGIT) DENOTES THE SEAT ROW, WITH CODE VALUES FROM 1 TO 5.

SECOND DIGIT


THE SECOND DIGIT (RIGHT DIGIT) DENOTES THE POSITION ON THE SEAT AND, IN SOME INSTANCES, THE WIDTH OF THE SEAT.

(1)	LEFT	(3) RIGHT	•••••		INDIVIDUAL SEAT
(1)	LEFT	(2) CENTER	(3)	RIGHT	BENCH: FULL WIDTH 3 PASSENGER
(1)	LEFT	(2) LEFT CENTER	(6)	RIGHT (3) RIGHTCENTER	BENCH: FULL WIDTH 4 PASSENGER
(1)	LEFT	(2) CENTER	(5)	RIGHT &AISLE SPACE	BENCH: PARTIAL WIDTH, LEFT
(0)	LEFT & SPACE	(2) CENTER	(5)	RIGHT &	BENCH: PARTIAL WIDTH, CENTERED
(4)	ENTIRE V	EHICLE WIDTH			CARGO AREA

EXAMPLES

THE TWO FIGURES BELOW PROVIDE EXAMPLES OF THE OCCUPANT SPACE NUMBER.





VAN 12 PASSENGER CAPACITY

X	X	11			13	
$x \times x$				21	22	25
$x \times x$				31	32	35
$x \times x$	X	41	42	46	43	

CODES FOR COLUMN F, MEASUREMENT AXIS

(X) X-AXIS (FORE & AFT)

(Y) Y-AXIS (LATERAL)

(Z) Z-AXIS (VERTICAL)

CODES FOR COLUMNS G, H, I & J, OCCUPANT & INJURY NUMBERS

INJURY	
NUMBER	CONTACT
(00)	-
(00)	NO CONTACT
(00)	CONTACT, NO INJURY
(99)	CONTACT, OCCUPANT UNKNOWN, INJURY UNKNOWN
(00) OR (99)	UNKNOWN IF CONTACT
	NUMBER (00) (00) (99)

IT-4 INTRUSION

CODES FOR COLUMN C, INTRUDING COMPONENT OR OBJECT

NOTE: DO NOT CODE OBJECTS OTHER THAN COMPONENTS OF CASE VEHICLE.

INDIVIDUAL COMPONENT

INTERNAL

(01) INSTRUMENT PANEL

(02) FIRE WALL

(03) TOE PAN

(04) FLOOR PAN

(05) STEERING COLUMN

(06) WINDSHIELD

(07) WINDSHIELD HEADER

(08) A-PILLAR

(09) DOOR PANEL OR SIDE PANEL

(10) WINDOW FRAME

(11) B-PILLAR

(12) C-PILLAR

(13) D-PILLAR

(14) ROOF SIDE RAILS

(15) ROOF OR CONVERTIBLE TOP

(16) BACKLIGHT HEADER

(17) FRONT SEAT-BACK SURFACE/ **SEAT-BACK BACK SURFACE**

(18) SECOND SEAT-BACK SURFACE SEAT-BACK BACK SURFACE

(19) THIRD SEAT-BACK SURFACE SEAT-BACK BACK SURFACE

(20) FOURTH SEAT-BACK SURFACE SEAT-BACK BACK SURFACE

(21) FIFTH SEAT-BACK SURFACE SEAT-BACK BACK SURFACE

(22) BACK PANEL/BACK DOOR SURFACE

(23) SEAT CUSHION SURFACE/EDGE

(24) CONSOLE

(25) OTHER (DESCRIBE)

(26) UNKNOWN INTERNAL SURFACES

(28) TRANSMISSION TUNNEL (HUMP)

(29) SIDE FOOTWELL PANEL (KICKPANEL)

(30) SILL

EXTERNAL

. .

(43) HOOD

(44) OBJECT EXTERNAL TO PASSENGER COMPARTMENT BUT PART OF CASE VEHICLE

(45) OUTSIDE SURFACE OF CASE VEHICLE

(46) OTHER (E.G. SPARE TIRE, JACK. DESCRIBE.)

(49) UNKNOWN EXTERNAL OBJECT

GROUPED FOR MASSIVE INTRUSION INTO AN OCCUPANT SPACE

USE ONLY IF ALL THESE COMPONENTS INTRUDED INTO A SINGLE OCCUPANT SPACE.

(50)WINDSHIELD HEADER

A-PILLAR

ROOF SIDE RAIL

(51)INSTRUMENT PANEL

A-PILLAR DOOR PANEL

(52)INSTRUMENT PANEL

A-PILLAR

WINDSHIELD HEADER

(53)DOOR PANEL

B-PILLAR **ROOF RAIL**

(54)DOOR PANEL A-PILLAR

ROOF RAIL

(55)INSTRUMENT PANEL

FLOOR PAN A-PILLAR

DOOR FRAME

(56) ROOF RAIL

A-PILLAR **B-PILLAR**

WINDOW FRAME

(57)ROOF RAIL

A-PILLAR **B-PILLAR** -

C-PILLAR

DOOR PANEL

(58)ROOF

ROOF RAIL

WINDOW FRAME

DOOR PANEL

(59)BACKLIGHT HEADER

ROOF

C-PILLAR

THIRD SEAT-BACK

(60)ROOF **ROOF RAIL** A-PILLAR

B-PILLAR C-PILLAR

WINDOW FRAME DOOR PANEL FLOOR PAN

(61)INSTRUMENT PANEL

TOE PAN

WINDSHIELD HEADER

A-PILLAR

ROOF RAIL WINDOW FRAME

DOOR PANEL **ROOF**

(62)ROOF **ROOF RAIL**

C-PILLAR

WINDOW FRAME

FLOOR PAN

SECOND SEAT

DOOR PANEL

(63)ROOF RAIL

ROOF

B-PILLAR WINDOW FRAME

FLOOR PAN

DOOR PANEL

SECOND SEAT

FRONT SEAT

(64) ROOF RAIL

ROOF OR CONVERTIBLE TOP A-PILLAR

B-PILLAR

WINDOW FRAME

WINDOW HEADER

(65)WINDSHIELD WINDSHIELD HEADER

ROOF SIDE RAIL

(66)WINDSHIELD WINDSHIELD HEADER

(98)NOT APPLICABLE

A-PILLAR

(99)UNKNOWN

	columns 1-8 previous card		<u>j</u> <u>T</u>	Format 0	1 12			Int	RUSION	IT-5				
(0) No (1) YI	O <u>DO NO</u> T	UPANT COM TANSWER NEX TRINEXT QUES SKIP PAGE.	CT QUESTI		-	V		ON CATAS COMPLETE PA SKIP PAGE.		14				
from the p	Duplicate columns 1-8 from the previous card. Module I g T Format 0 2 11 12 NOTE: Each line in the table below is a separate record (card). Duplicate columns 1 - 12 for each completed line. INTRUSIONS CODE INTRUSIONS IN THIS ORDER: LEFT TO RIGHT ON ROW; FRONT TO BACK IN VEHICLES. CODES FOR B, F, G, H, I, J ON PAGE IT-3 CODES FOR C ON PAGE IT-4 OCCUPANT CONTACT AND INJURY													
A INTRUSION NUMBER	B OCC. SPACE NO.	C INTRUDING COMPONENT OR OBJECT	D ASSOC. EVENT NO.		F MAXIMUM INTRUSION Y AXIS (cm)	G MAXIMUM INTRUSION Z AXIS (cm)	H OCCUPANT NUMBER	I INJURY NUMBER	J OCCUPANT NUMBER	K INJURY NUMBER				
13-14	15-16	17-18	19	20-21	22-23	24-25	26-27	28-29	30-31	32-33				
0 1	11	04	1	00	00	06 of	00	00	00	00				
0 2														
0 4														
0 5														
0 6			_											
0 7 NOTE: USE	 E ADDITIONAL F	PAGE IF MORE TH	 IAN 7 INTRU	USIONS.										
	columns 1-8 revious card		I T 10	Format 0	_									
SKIP SIDE D RES	DOOR INT BULTED F	RUSION		IF DA DOOF INTRU: NUMBE A	RINTRUS SION ER CO	DOOR CO ION, CODE DAMAGED DMPONENT 1	DAMA COMPONE DAMA COMPO	ENT AGED NENT 2	CODES' FOR COMPONE (0) NONE (1) A-PILLAR (2) B-PILLAR (3) C-PILLAR (4) LATCH/STR (5) HINGES (7) OTHER: (8) NOT APPLIC (9) UNKNOWN	ENTS IKER				

Duplicate columns 1-8 from the previous card.

INTRUSION

IT-6

NOTE: Each line in the table below is a separate record (card).

Duplicate columns 1 - 12 for each completed line.

-- ADDITIONAL PAGE --

INTRUSIONS CODE INTRUSIONS IN THIS ORDER: LEFT TO RIGHT ON ROW, FRONT TO BACK IN VEHICLES.

CODES FOR B, F, G, H, I, J ON PAGE IT-3

CODES FOR C ON PAGE IT-4

OCCUPANT CONTACT AND INJURY

		CODES :	OCCUPAN	OCCUPANT CONTACT AND INJURY						
A INTRUSION NUMBER	B OCC. SPACE NO.	C INTRUDING COMPONENT OR OBJECT		-	F MAXIMUM INTRUSION Y AXIS (cm)		H OCCUPANT NUMBER	I INJURY NUMBER	J OCCUPANT NUMBER	K INJURY NUMBER
13-14	15-16	17-18	19	20-21	22-23	24-25	26-27	28-29	30-31	32-33
0 8										
<u> </u>										
1 0										
1 1										
1 2										
1 3										
1 4										
<u>1</u> <u>5</u>										
<u>1</u> 6										
1 7			_							
1 8						 .				
1 9										
20										
2 1							 .			
22										
2 3										
24							_ — —			
2 5								——		
								<u>. </u>		

Duplicate columns 1-8 from the previous card.	Modu	le <u>I</u> <u>D</u> 9 10	Format <u>0</u> <u>1</u>	ln	TERIOR DAMAGE I)-1
CO	(1) NO) YES) NO, and	OCCUPANT CONTACT	(4) YES, and C (8) NOT APPL (9) UNKNOWN	DCCUPANT CONTACT ICABLE	
SIDES FRONT DOOR FRONT HARDWARE FRONT ARMREST FRONT GLASS REAR DOOR AREA REAR HARDWARE REAR ARMREST REAR GLASS ROOF SIDE RAIL B-PILLAR C-PILLAR D-PILLAR HEADLINING ROOF STRUCTURE T-ROOF/SUN ROOF		RIGHT 0 14 0 15 0 12 6 2 6 2 6 2 6 2 6 2 6 2 6 2 6 2 6 2	FRONT FOOT CONTROLS IGNITION KEYS REAR VIEW MIRROR SUNVISOR/FITTINGS (5) LEFT SIDE ONLY (6) RIGHT SIDE ONLY (7) BOTH SIDES WINDSHIELD TOP MOLDINGS LEFT A-PILLAR (UPPER OR LOWER) RIGHT A-PILLAR (UPPER OR LOWER) CENTER CONSOLE TRANSMISSION SELECTOR LEVER RIM, HORN, SPOKE	14 0 4 0 4 0 5 0 5 0 5 0 5 0 5 0 5 0 5 0	INSTRUMENT PANEL UPPER PANEL MID PANEL LOWER PANEL ASHTRAY CONTROL KNOBS & LEVERS GLOVE COMPARTMENT AREA INSTRUMENTS PARKING BRAKE RELEASE PARKING BRAKE PEDAL A/C OR UPPER VENT OUTLETS HEATER OR A/C DUCTS RADIO OTHER: *	3 55 4 55 4 55 6 55 6 66 6 67 82 6 83 6 84 6 85 6 84 6 85 6 8
OTHER: *	00 do 20	8 4			REAR WINDOW WINDOW HEADER	68 69
3 . 2				_	CONSOLES VERTICAL ROOF	70 71

^{*} MORE THAN ONE ITEM MAY BE NOTED.

Duplicate columns 1-8 Module S T from the previous card. 9 10		1 2	SEATS	,	ST-1
FRONT SEAT TYPE OF FRONT SEAT (00) NO SEAT	DRIVER	PASSENTR	FRONT SEAT-BACK	DRIVER	PASSEN'R
(01) STANDARD BENCH (02) SPLIT BACK, 50-50 (03) SPLIT BACK, DRIVER WIDE (04) SPLIT BACK, PASS. WIDE (05) BUCKET (06) CAPTAIN'S CHAIR (07) INDIV. BENCH, 50-50 (08) INDIV. BENCH, DRIVER WIDE (09) INDIV. BENCH, PASS. WIDE	05	15 16	SEAT-BACK TYPE (1) FORWARD FOLDING (2) RIGID (3) RECLINING (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN	3 30	3
(97) OTHER:	17	18	SEAT-BACK LOCK TYPE (0) NONE (1) MANUAL (2) INERTIA (3) POWER (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN	32	33
SWIVEL MECHANISM EQUIPPED	19	20	LOCKS HELD (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	34	35
ORIGINAL EQUIPMENT SEATS (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	1 21		RECLINER MECHANISM HELD (0) NO	1	_(
CONTACT OF SEAT BY REAR OCCUPANT (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	8 23	24	(1) YES (8) NOT APPLICABLE (9) UNKNOWN	36	37
FRONT SEAT DAMAGE (0) NONE (1) BACKREST ONLY DAMAGED (2) CUSHION ONLY DAMAGED (3) BACKREST & CUSHION DAMAGED (8) NOT APPLICABLE (9) UNKNOWN	25	<u>O</u> 26	HEAD RESTRAINT HEAD RESTRAINT TYPE (0) NONE (1) ADJUSTABLE (2) INTEGRAL (3) NOT INTEGRAL, BUT CANNOT BE REMOVED (7) OTHER: (8) NOT APPLICABLE	2 38	<u>2</u>
CENTER ARMREST DAMAGED (0) NO (1) YES (7) EQUIPPED, DAMAGE UNKNOWN (8) NOT APPLICABLE (NO CENTER ARMREST) (9) UNKNOWN IF EQUIPPED	27	ַ	(9) UNKNOWN REMOVED PRE-CRASH (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	8 40	8
FRONT SEAT ROTATION (0) NONE APPARENT	0	0	ADJUSTMENT AT CRASH (1) UP (2) DOWN (8) NOT APPLICABLE (9) UNKNOWN	42	8 43
(0) NONE APPARENT (1) FORWARD APPARENT (2) REARWARD APPARENT (3) LEFT APPARENT (4) RIGHT APPARENT (5) MULTIPLE ROTATIONS SPECIFY (8) NOT APPLICABLE (9) UNKNOWN	28	29	HEAD RESTRAINT DAMAGE (0) NONE (+) DAMAGED BUT NOT SEPARATED (2) SEPARATED (8) NOT APPLICABLE (9) UNKNOWN	<u>Ø</u>	<u>O</u>

-			Si	EATS S	ST-2
FRONT SEAT ADJUSTMENT SEAT ADJUSTMENT TYPE	DRIVER	Passen'r	SECOND SEAT (CONT.)		
(0) NONE (RIGID) (1) MANUAL (2) POWER (7) OTHER: (8) NOT APPLICABLE (NO SEAT) (9) UNKNOWN	46	47	CENTER ARMREST DAMAGED (0) NO (1) YES (7) EQUIPPED, DAMAGE UNKNOWN (8) NOT APPLICABLE	<u> </u>	§
ADJUSTMENT PROVIDED (1) 2-WAY (2) 4-WAY (3) 6-WAY (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN	48	49	(9) UNKNOWN IF EQUIPPED SECOND SEAT-BACK LOCKS	LEFT	Rіgнт
SEAT ADJUSTER DAMAGE (0) NONE (1) CHUCKING (FREE PLAY) (2) DEFORMED (RELEASED/JAMMED) (3) SEPARATED (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN	50	51	FOR THE FOLLOWING, USE: (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	æ	ç
SEAT ADJUSTER SEPARATION (0) NONE (1) SEPARATED AT FLOOR (2) SEPARATION OF ADJUSTER (3) SEPARATED AT SEAT (8) NOT APPLICABLE (9) UNKNOWN	52	53	LEFT OR CENTER, EQUIPPED LEFT OR CENTER, HELD (3) SEAT FOLDED DOWN RIGHT, EQUIPPED	4 6 8 9 8 9 8 9	6 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8
PRE-CRASH POSITION (1) FORWARD (2) MIDDLE (3) REARWARD (8) NOT APPLICABLE (9) UNKNOWN	54	3 55	RIGHT, HELD (3) SEAT FOLDED DOWN THIRD SEAT	67	<u>8</u>
SECOND SEAT TYPE OF SECOND SEAT (0) NONE	LEFT	Rіgнт	EQUIPPED BACKREST DAMAGED	69	0 70 8 72
- (1) NON-FOLDING - (2) FOLDING (3) CAPTAIN'S CHAIR (4) JUMP SEAT (5) INTEGRAL CHILD SEAT	<u>O</u> 56	57	CUSHION DAMAGED	73	<u>څ</u>
(6) LUGGAGE AREA ACCESS PANEL (9) UNKNOWN SECOND SEAT DAMAGE (0) NONE (1) BACKREST ONLY (DAMAGED OR LOOSENED) (2) CUSHION ONLY (DAMAGED OR LOOSENED) (3) BACKREST & CUSHION (DAMAGED OR LOOSENED) (4) INTEGRAL CHILD SEAT (PBIORITY CODE) (5) LUGGAGE AREA ACCESS PANEL (DAMAGED OR LOOSENED) (8) NOT APPLICABLE (9) UNKNOWN	8 58	59	VEHICLE EQUIPPED WITH REAR HEAD RESTRAINTS (0) NOT EQUIPPED (OR REMOVED) (1) EQUIPPED (2) EQUIPPED & DAMAGED (8) NOT APPLICABLE (NO REAR SEAT) (9) UNKNOWN Applies to any rear-seat position	71	<u>}</u>

Duplicate columns 1-8 Module A B Format 0 11 Trom the previous card.	1 12	AIRBAG	AB-1
DRIVER SIDE LOCATION OF AIRBAG STEERING WHEEL EQUIPPED (0) NO (1) YES (4) PRIOR DEPLOYMENT NOT REINSTALLED (9) UNKNOWN IF AIRBAG EQUIPPED	13	PASSENGER SIDE LOCATION OF AIRBAG INSTRUMENT PANEL (GLOVE BOX) EQUIPPED (0) NO (1) YES (4) PRIOR DEPLOYMENT NOT REINSTALLED (9) UNKNOWN IF AIRBAG EQUIPPED	16
(0) NO (1) YES (2) PARTIAL/IMPROPER DEPLOYMENT (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN	14	(0) NO (1) YES (2) PARTIAL/IMPROPER DEPLOYMENT (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN	<u>Q</u>
CONDITION OF AIRBAG STEERING WHEEL (0) NO DAMAGE (2) SPLIT OR TORN (3) CUT DURING CRASH (4) BURNED/MELTED (5) CUT POST CRASH (6) OTHER (7) DAMAGED, CONDITION UNKNOWN (8) NOT APPLICABLE (NOT EQUIPPED/NOT DEPLOYED) (9) UNKNOWN IF EQUIPPED OR CONDITION	15	CONDITION OF AIRBAG INSTRUMENT PANEL (GLOVE BOX) (0) NO DAMAGE (2) SPLIT OR TORN (3) CUT DURING CRASH (4) BURNED/MELTED (5) CUT POST CRASH (6) OTHER (7) DAMAGED, CONDITION UNKNOWN (8) NOT APPLICABLE (NOT EQUIPPED/NOT DEPLOYED) (9) UNKNOWN IF EQUIPPED OR CONDITION	8
DRIVER SIDE AIRBAG STEERING WHEEL TETHER (0) NO (1) YES (6) OTHER (7) UNKNOWN IF TETHERED (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN IF AIRBAG EQUIPPED	19	PASSENGER SIDE AIRBAG INSTRUMENT PANEL (GLOVE BOX) TETHER (0) NO (1) YES (6) OTHER (7) UNKNOWN IF TETHERED (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN IF AIRBAG EQUIPPED	21
MARKED BY CONTACT (0) NO (1) YES (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN	20	MARKED BY CONTACT (0) NO (1) YES (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN	8 2

٠.

AIRBAG AB-2 **Driver Airbag** AIRBAG NUMBER ON DRIVER SIDE: P118137-03H TAC320M12045 **Driver Airbag Doors** 54 20 **BLOOD** 15 48 H-Pattern Vents: Y N Tethers: Y if yes, how many: _ if yes, how many: __ AIRBAG NUMBER ON PASSENGER SIDE: NOTE AND DESCRIBE ANY AIRBAG CONTACT OR DAMAGE ON DIAGRAM BELOW:

NOTE TO THE INVESTIGATOR:

THE FOLLOWING TWO SECTIONS,
OCCUPANT INFORMATION AND INJURY CLASSIFICATION,
ARE TO BE FILLED IN
FOR EACH CASE VEHICLE OCCUPANT,
WHETHER INJURED OR NOT.

IF THERE IS MORE THAN ONE OCCUPANT,
USE ADDITIONAL COPIES
OF PAGES OC-1, OC-2, OC-3,
AND IC-2 TO DESCRIBE THEM
AND ATTACH THE COPIES TO THIS REPORT.


Duplicate columns 1-8 Module O C Format 0 11	OCCUPANT INFORMATION OC-1				
OCCUPANT IDENTIFICATION OCCUPANT NUMBER ROLE OF OCCUPANT AT 1ST IMPACT (1) MOTOR VEHICLE DRIVER (2) MOTOR VEHICLE PASSENGER (NOT DRIVER) (9) UNKNOWN	13 14	PHYSICAL DESCRIPTION AGE IN YEARS (00) LESS THAN 1 YEAR (98) 98 YEARS OR OLDER (99) UNKNOWN AGE IN MONTHS (00) LESS THAN 1 MONTH (25) 25 MONTHS OR OLDER (99) UNKNOWN	$\frac{6}{20} \frac{1}{21}$ $\frac{2}{22} \frac{5}{23}$		
OCCUPANT POSITION ROW LOCATION (1) FRONT (2) SECOND (3) THIRD (4) FOURTH (7) OTHER: (8) EXTERNAL TO PASSENGER COMPARTMENT (E.G. BED OF PICKUP) (9) UNKNOWN	16	MASS (kg) (999) UNKNOWN HEIGHT (cm) (999) UNKNOWN SEX (1) MALE (2) FEMALE (9) UNKNOWN	054 24 25 28 163 27 28 29 2		
LATERAL LOCATION (1) LEFT (2) LEFT CENTER (3) CENTER (4) RIGHT CENTER (5) RIGHT (6) ALL (LYING ON SEAT) (8) EXTERNAL TO PASSENGER COMPARTMENT (9) UNKNOWN	17	MEDICAL CONDITIONS TREATMENT/MORTALITY (00) NONE (01) FIRST AID AT SCENE (02) TREATED AT HOSPITAL/CLINIC BUT NOT ADMITTED (03) HOSPITALIZED FOR OBSERVATION LESS THAN 24 HOURS (04) HOSPITALIZED OVER 24 HOURS OR FOR SIGNIFICANT TREATMENT (05) FATAL, DEAD AT SCENE (06) FATAL, DOA	<u>O</u> ¥ 31 32		
(10) SITTING ON SEAT (11) SITTING ON SEAT IN ABNORMAL POSITION (E.G. FEET ON DASH, SIDEWAYS) (12) SITTING ON CONSOLE (20) ON LAP OR IN ARMS (30) STANDING ON SEAT (40) STANDING ON FLOOR (47) STANDING, EXTERNAL TO PASSENGER COMPARTMENT (50) IN BASSINET (60) IN CHILD SEAT (65) IN CHILD HARNESS (70) LYING ON SEAT (80) LYING/SITTING ON PASSENGER FLOOR (83) LYING/SITTING ON OTHER OBJECT IN PASSENGER COMPARTMENT: (85) ON CARGO FLOOR/FOLDED SEAT-BACK (87) LYING/SITTING, EXTERNAL TO PASSENGER COMPARTMENT (97) OTHER: (99) UNKNOWN	10 18 19	(07) FATAL, DEAD WITHIN 24 HOURS (08) FATAL, DEAD 24 HOURS TO 31 DAYS LATER (09) FATAL, DEAD 31 DAYS TO 1 YEAR LATER (10) FATAL DEAD WITHIN UNKNOWN PERIOD (99) UNKNOWN INJURY SEVERITY SCORE (ISS) (99) UNKNOWN NON-IMPACT MED. CONDITIONS (0) NONE (1) YES, TIME & TYPE UNKNOWN (2) PRE-CRASH FATAL (CLINICAL DEATH AT WHEEL) (3) PRE-CRASH NON-FATAL (E.G. PRIOR INJURY, STROKE) (4) PREGNANT (5) POST-CRASH FATAL (DROWNING) (6) POST-CRASH NON-FATAL INJURY (7) OTHER: (8) COMBINATION OF ABOVE (CIRCLE EACH) (9) UNKNOWN	33 34		

-		OCCUPANT INFORMATION (DC-2
MEDICAL CONDITIONS (CONT.) POLICE INJURY SEVERITY CODE FOR THIS OCCUPANT (0) O - NO INJURY (1) C - POSSIBLE INJURY (2) B - NON-INCAPACITATING (3) A - INCAPACITATING INJURY (4) K - FATAL (5) INJURED, SEVERITY UNKNOWN (6) DIED PRIOR TO IMPACT (7) NON-FATAL INJURY, SEVERITY UNKNOWN (9) UNKNOWN	3 36	CHILD SEAT TYPE (00) NONE USED (01) YES, USED (02) INTEGRAL, Chrysler Mini-van (88) NOT APPLICABLE (ADULT OR OLDER CHILD) (99) UNKNOWN CHILD SEAT MAKE/MODEL	8 41 42
RESTRAINT SYSTEM (0) NONE (1) LAP BELT (2) SHOULDER HARNESS ONLY (3) BOTH LAP BELT & SHOULDER HARNESS (9) UNKNOWN ACTIVE RESTRAINT SYSTEM USAGE (0) NONE (AVAILABLE BUT NOT USED) (1) LAP BELT & SHOULDER HARNESS ONLY (2) SHOULDER HARNESS ONLY (3) BOTH LAP BELT & SHOULDER HARNESS (7) IMPROPER USAGE (8) NOT APPLICABLE (NONE AVAILABLE) (9) UNKNOWN PASSIVE RESTRAINT SYSTEM (0) NONE (1) AIRBAG INSTALLED (2) PASSIVE UPPER TORSO WITH KNEE BOLSTERS (3) PASSIVE UPPER TORSO WITHOUT KNEE BOLSTERS (4) PASSIVE LAP & UPPER TORSO (5) AIRBAG INSTALLED & PASSIVE RESTRAINT (7) OTHER: (9) UNKNOWN PASSIVE RESTRAINT SYSTEM USAGE (0) SYSTEM DEFEATED (1) AIRBAG NOT DEPLOYED	3 37	EJECTION DEGREE OF EJECTION (0) NONE (1) PARTIAL (2) COMPLETE (7) EJECTED, DEGREE UNKNOWN (9) UNKNOWN IF EJECTED AREA OF EJECTION (01) WINDOW, LEFT SIDE (02) WINDOW, RIGHT SIDE (03) WINDOW, REAR (04) DOOR, LEFT SIDE (05) DOOR, RIGHT SIDE (06) DOOR, REAR OR TAILGATE (07) WINDSHIELD (08) ROOF OR OPEN CONVERTIBLE OR FROM EXTERNAL AREA (96) EJECTED AREA UNKNOWN (97) OTHER AREA: (98) NOT APPLICABLE (NOT EJECTED) (99) UNKNOWN IF EJECTED	O 43 98 44 45
(2) AIRBAG DEPLOYED (3) AIRBAG NOT REINSTALLED (4) PASSIVE UPPER TORSO USED (5) PASSIVE LAP & UPPER TORSO USED (6) SYSTEM USED IN MANUAL MODE (7) IMPROPER USAGE (8) NOT APPLICABLE (NOT ORIGINALLY EQUIPPED) (9) UNKNOWN	A *	HEAD RESTRAINT HEAD RESTRAINT AVAILABLE FOR THIS POSITION (0) NOT EQUIPPED OR REMOVED (1) EQUIPPED (9) UNKNOWN	46

OCCUPANT INFORMATION OC-3								
OCCUPANT EYEWEAR (0) NONE (1) GLASSES (2) CONTACTS (3) BOTH GLASSES AND CONTACTS (4) OTHER (8) NOT APPLICABLE (9) UNKNOWN	47	SOURCE OF INFORMATION (1) HOSPITAL (2) AUTOPSY (3) POLICE (4) OTHER (5) LAY CORONER/EXTERNAL EXAM (7) COMBINATION OF ABOVE (CIRCLE) (8) NOT APPLICABLE (9) UNKNOWN	48					

OCCUPANT INFORMATION OC-4

INDICATE LOCATION OF INJURIES.



Puplicate columns 1-8 from the previous card.

INJURY CLASSIFICATION IC-1

NOTE: Each line in the table below is a separate record (card).

Duplicate columns 1 - 12 for each completed line.


	Occui	DANT	NURV	CL	ASSIFICATION
--	-------	------	------	----	--------------

Occupant Injury Classification														
				PRIMARY OIC					ASSOCIATED OIC				COMMENTS	
INJURY NUMBER	PROBAI START IN 1ST 0	BILITY (HOF WITH MOST CONTACT A	RIZONTALLY) . PROBABLE BREA COLUMN.	BODY REGION 1	ASPECT O	LESION (7)	SYSTEM/ORGAN 4	SEVERITY 45	BODY REGION 1	ASPECT N	TESION 3	SYSTEM/ORGAN 4	SEVERITY 15	
15-16	17-18	19-20	COMMENTS	21	22	23	24	25	26	27	28	29	30	
OL	10			E	5	<u></u>	I	1	_		_			
02	65	87		<u>C</u>	<u> </u>	F	<u>ح</u>	2		_		_	_	
03	65	87		_ <u>_</u>	<u>_</u>	<u>८</u>	2	3_	_					
04	48	07		K	<u>_</u>	E	<u>s</u>	2_			_	_		
05	48	07	n arki	4	<u>_</u>	F	<u>5</u>	ح	_		_			
06	48	07	Brake home	<u> </u>	<u>८</u>	E	<u>5</u>	2	_	_	_	_	_	
07	<u>28</u>		Brake pely		R	F	<u>5</u>	2	_		_	_	_	
											_	_		
					_							_		
				_	_	_				_		_		
				_	_			_			_			
							_	_	-				_	
						_	_		_			_		
								_			_			
				_					-		_			
				_			_	-	_				_	
→				_		_	_		-	_	_		-	
USE ACCU	7004 24	ZEQ IE NIFO	ESCARY		_				_			_	-	
	15-16 Q1 Q2 Q3 Q4 Q5	PLACE PROBA START IN 15T OF AREA(S 1ST) 15-16 17-18 OL 10 02 65 03 65 04 48 07 28	PLACE CONTACTS PROBABILITY (HOR START WITH MOST IN 1ST CONTACT A AREA(S) OF POSSI 1ST 2ND	PLACE CONTACTS IN ORDER OF PROBABILITY (HORIZONTALLY). START WITH MOST PROBABLE IN 1ST CONTACT AREA COLUMN. AREA(S) OF POSSIBLE CONTACT 1ST 2ND 15-16 17-18 19-20 COMMENTS OI 10 02 65 87 04 48 07 06 48 07 Brake hard (clease	PLACE CONTACTS IN ORDER OF PROBABILITY (HORIZONTALLY). START WITH MOST PROBABLE IN 1ST CONTACT AREA COLUMN. AREA(S) OF POSSIBLE CONTACT 1ST 2ND 15-16 17-18 19-20 COMMENTS 21 Q1 10	PRIME PRIME PROBABLE PROBABLE IN 1ST CONTACT AREA COLUMN. AREA(S) OF POSSIBLE CONTACT 1 2 15-16 17-18 19-20 COMMENTS 21 22 O1 10	PRIMARY (PLACE CONTACTS IN ORDER OF PROBABILITY (HORIZONTALLY) START WITH MOST PROBABLE IN 1ST CONTACT AREA COLUMN. AREA(S) OF POSSIBLE CONTACT 1ST 2ND 15-16 17-18 19-20 COMMENTS 21 22 23 OI 10	PRIMARY OIC PLACE CONTACTS IN ORDER OF PROBABILITY (HORIZONTALLY). START WITH MOST PROBABLE IN 1ST CONTACT AREA COLUMN. AREA(S) OF POSSIBLE CONTACT 1ST 2ND 1 2 3 4 15-16 17-18 19-20 COMMENTS 21 22 23 24 OI 10	PRIMARY OIC PLACE CONTACTS IN ORDER OF PROBABILITY (HORIZONTALLY). START WITH MOST PROBABLE IN 1ST CONTACT AREA COLUMN. AREA(S) OF POSSIBLE CONTACT 15-16 17-18 19-20 COMMENTS 21 22 23 24 25 OI 10	PRIMARY OIC A PLACE CONTACTS IN ORDER OF PROBABILITY (HORIZONTALLY). PRIMARY OIC A PLACE CONTACTS IN ORDER OF PROBABLE IN IST CONTACT AREA COLUMN. AREA(S) OF POSSIBLE CONTACT 1ST 2ND 15-16 17-18 19-20 COMMENTS 21 22 23 24 25 26 O1 10	PRIMARY OIC ASSOCIATION OF THE PROBABILITY (HORIZONTALTY). START WITH MOST PROBABLE. IN 15T CONTACT AREA COLUMN. AREA(S) OF POSSIBLE CONTACT 1ST 2ND 15-16 17-18 19-20 COMMENTS 21 22 23 24 25 26 27 O1 10	PRIMARY OIC ASSOCIATED	PRIMARY OIC ASSOCIATED OIC PRIMARY OIC ASSOCIATED OIC PROBABILITY (HORIZONTALLY) START WITH MOST PROBABLE INST 2ND AREA(S) OF POSSIBLE CONTACT 1ST 2ND 15-16 17-18 19-20 COMMENTS 21 22 23 24 25 26 27 28 29 OI 10	PRIMARY OIC ASSOCIATED OIC PROBABility (HORIZONTALLY) START WITH MOST PROBABLE BY

INJURY CLASSIFICATION IC-2

CODES FOR AREAS OF POSSIBLE OCCUPANT CONTACT

1				
	FRONT	OF PASSENGER COMPARTMENT	SIDES	
1		SUNVISOR, FITTING(S) &/OR TOP MOLDING	(20)	SURFACE OF SIDE INTERIOR
1	(12)	• •	• •	
1	(12)	WINDONIELD	(19)	HARDWARE ON SIDE OR DOOR
			. (13)	ARMREST ON SIDE OR DOOR
1	(05)	,	(24)	COAT HOOK
1	(54)	UPPER INSTRUMENT PANEL (X)	•	
	(55)	MIDDLE INSTRUMENT PANEL (Y)	(22)	WINDOW GLASS (SIDE)
1	(56)	, , ,	(21)	WINDOW FRAMES (SIDE)
1		• • • • • • • • • • • • • • • • •	(21)	WINDOW FRANCS (SIDE)
	(81)	· · · · · · · · · · · · · · · · · · ·		
1	(02)		(26)	ROOF SIDE RAIL
1	(47)	AIRBAG (ACRS) COMPARTMENT DOOR/COVER	(14)	A-PILLAR
			(15)	B-PILLAR
1	(57)	BENEATH INSTRUMENT PANEL	, ,	C-PILLAR
	(53)		• •	D-PILLAR
1			(17)	D-PILLAN
	(48)		-	
	(86)	VERTICAL CONSOLE	FLOOR	
1			(40)	FLOOR
1	(28)	FOOT CONTROLS (INCL. PARKING BRAKE PEDAL)	(27)	CONSOLE ON FLOOR OR BETWEEN SEATS
				TRANSMISSION LEVER ON FLOOR OR CONSOLE
	(09)	STEERING ASSEMBLY (SPECIFIC AREA UNKNOWN)		PARKING BRAKE HANDLE ON FLOOR OR CONSOLE
1		·		
	(65)	STEERING WHEEL		FOOT CONTROLS (INCL. PARKING BRAKE PEDAL)
	_ (66)	STEERING WHEEL COLUMN	(91)	KICKPANEL
ı	(59)	TRANSMISSION LEVER ON COLUMN		
İ			Roof	
	(03)	HARDWARE ITEM (SPECIFIC AREA UNKNOWN)		ROOF OR CONVERTIBLE TOP
1	(82)	INSTRUMENT(S)	, ,	
1		· ·		SUNVISOR, FITTING(S) &/OR TOP MOLDING
1	(83)	CONTROL KNOB(S) & LEVER(S) (FRONT)	• •	ROOF SIDE RAIL
1	(84)	PARKING BRAKE HANDLE IN FRONT	(24)	COAT HOOK
1	(67)	IGNITION KEY	(18)	DOME LIGHT
	(06)	MIRROR	(39)	BACKLIGHT HEADER
1	(04)	HEATER OR AIR CONDITIONING DUCTS		ROOF MOUNTED CONTROLS/CONSOLE
1				
ı	(01)	AIR CONDITIONING OR VENTILATION OUTLET(S)	(69)	ROLL BAR
1	(08)	RADIO (BUILT IN)	_	
1	(58)	ADD-ON TAPE DECK, RADIO, A/C	EXTERIO	OR SURFACE OF CASE VEHICLE
	(68)	ROOF MOUNTED CONTROLS/CONSOLES	(37)	OUTSIDE SURFACE OF CASE VEHICLE
1	, ,		(4.7	(SPECIFIC AREA UNKNOWN)
ļ	REAR		(05)	•
			(35)	HOOD OF CASE VEHICLE
1	(88)	SURFACE OF REAR INTERIOR	(60)	EXTERIOR OF CASE VEHICLE (E.G.
1	(23)	REAR WINDOW		OUTSIDE MIRRORS, ANTENNA, TRIM)
1	(39)	REAR WINDOW HEADER	(62)	EXTERIOR SIDE ROOF RAIL OF CASE VEHICLE
	(50)	REAR SEAT CUSHION & BACK	(63)	TRUNK LID OF CASE VEHICLE
1	(55)		(64)	
	INTERIOR	R-GENERAL	(04)	TIRES OF CASE VEHICLE
Į.			D	0 1/ 0.
		TRANSMISSION SELECTION LEVER (LOCATION UNK.)	REJOND	CASE VEHICLE BOUNDARY
1	(59)	TRANSMISSION LEVER ON STEERING COLUMN	(36)	AREA EXTERIOR TO CAR (SPECIFIC AREA UNK.)
1	(44)	TRANSMISSION LEVER ON FLOOR OR CONSOLE	(70)	HOOD OF OTHER VEHICLE
1	(07)		(71)	OTHER VEHICLE EXTERIOR HARDWARE (E.G.
I_	(84)	PARKING BRAKE HANDLE IN FRONT	(* ')	= 1=:=:
				OUTSIDE MIRRORS, ANTENNA, TRIM)
	(85)	PARKING BRAKE HANDLE ON FLOOR OR CONSOLE	(73)	EXTERIOR SIDE ROOF RAIL OF OTHER VEHICLE
	(28)	FOOT CONTROLS (INCL. PARKING BRAKE PEDAL)	(74)	HEADLIGHT OR FRONT GRILL OF OTHER VEH.
1			(75)	TRUNK OF OTHER VEHICLE
1	(29)	FRONT SEAT-BACK(S)	(76)	OUTSIDE SURFACE OF OTHER VEHICLE
	(51)		(77)	TIRES OF OTHER VEHICLE
1		REAR SEAT CUSHION & BACK		
1	, <i>,</i>		(78)	GROUND
l	(49)		(79)	WATER .
l	(89)	UNDER SEAT BOTTOM	(80)	EXTERIOR OBJECT (NOT VEHICLE, GROUND.
l			, ,	OR WATER. PLEASE DESCRIBE.)
1		RESTRAINT SYSTEM HARDWARE		•·· · · · · · · · · · · · · · · · · · ·
	(33)			
	(33)		Devero	ATING OD IFOTO
	(34)	RESTRAINT SYSTEM WEBBING		ATING OBJECTS
	(34) (87)	RESTRAINT SYSTEM WEBBING AIR CUSHION SKIN <i>(AIRBAG)</i>		ATING OBJECTS OTHER VEHICLE
	(34)	RESTRAINT SYSTEM WEBBING AIR CUSHION SKIN <i>(AIRBAG)</i>	(61)	
	(34) (87)	RESTRAINT SYSTEM WEBBING AIR CUSHION SKIN (AIRBAG) AIRBAG (ACRS) COMPARTMENT DOOR/COVER	(61)	OTHER VEHICLE
	(34) (87) (47) (46)	RESTRAINT SYSTEM WEBBING AIR CUSHION SKIN (AIRBAG) AIRBAG (ACRS) COMPARTMENT DOOR/COVER AIRBAG GAS	(61) (72)	OTHER VEHICLE OBJECTS (DESCRIBE)
	(34) (87) (47) (46) (48)	RESTRAINT SYSTEM WEBBING AIR CUSHION SKIN (AIRBAG) AIRBAG (ACRS) COMPARTMENT DOOR/COVER AIRBAG GAS KNEE RESTRAINT	(61) (72) M ISCELL	OTHER VEHICLE OBJECTS (DESCRIBE) ANEOUS
	(34) (87) (47) (46) (48) (30)	RESTRAINT SYSTEM WEBBING AIR CUSHION SKIN (AIRBAG) AIRBAG (ACRS) COMPARTMENT DOOR/COVER AIRBAG GAS KNEE RESTRAINT HEAD RESTRAINT	(61) (72) MISCELL (00)	OTHER VEHICLE OBJECTS (DESCRIBE) ANEOUS NO CONTACT (INVALID FIELD FORM CODE)
÷	(34) (87) (47) (46) (48) (30) (42)	RESTRAINT SYSTEM WEBBING AIR CUSHION SKIN (AIRBAG) AIRBAG (ACRS) COMPARTMENT DOOR/COVER AIRBAG GAS KNEE RESTRAINT HEAD RESTRAINT CHILD SEAT RESTRAINTS	(61) (72) MISCELL (00) (38)	OTHER VEHICLE OBJECTS (DESCRIBE) ANEOUS NO CONTACT (INVALID FIELD FORM CODE) OTHER (E.G. FIRE. DESCRIBE)
主	(34) (87) (47) (46) (48) (30) (42)	RESTRAINT SYSTEM WEBBING AIR CUSHION SKIN (AIRBAG) AIRBAG (ACRS) COMPARTMENT DOOR/COVER AIRBAG GAS KNEE RESTRAINT HEAD RESTRAINT CHILD SEAT RESTRAINTS CHILD SEAT	(61) (72) MISCELL (00) (38) (90)	OTHER VEHICLE OBJECTS (DESCRIBE) ANEOUS NO CONTACT (INVALID FIELD FORM CODE) OTHER (E.G. FIRE. DESCRIBE) SPARE TIRE
主	(34) (87) (47) (46) (48) (30) (42) (43) (31)	RESTRAINT SYSTEM WEBBING AIR CUSHION SKIN (AIRBAG) AIRBAG (ACRS) COMPARTMENT DOOR/COVER AIRBAG GAS KNEE RESTRAINT HEAD RESTRAINT CHILD SEAT RESTRAINTS CHILD SEAT INTERIOR LOOSE OBJECT	(61) (72) MISCELL (00) (38) (90)	OTHER VEHICLE OBJECTS (DESCRIBE) ANEOUS NO CONTACT (INVALID FIELD FORM CODE) OTHER (E.G. FIRE. DESCRIBE)
主	(34) (87) (47) (46) (48) (30) (42) (43) (31)	RESTRAINT SYSTEM WEBBING AIR CUSHION SKIN (AIRBAG) AIRBAG (ACRS) COMPARTMENT DOOR/COVER AIRBAG GAS KNEE RESTRAINT HEAD RESTRAINT CHILD SEAT RESTRAINTS CHILD SEAT INTERIOR LOOSE OBJECT	(61) (72) MISCELL (00) (38) (90)	OTHER VEHICLE OBJECTS (DESCRIBE) ANEOUS NO CONTACT (INVALID FIELD FORM CODE) OTHER (E.G. FIRE. DESCRIBE) SPARE TIRE
主	(34) (87) (47) (46) (48) (30) (42) (43) (43) (31) (32)	RESTRAINT SYSTEM WEBBING AIR CUSHION SKIN (AIRBAG) AIRBAG (ACRS) COMPARTMENT DOOR/COVER AIRBAG GAS KNEE RESTRAINT HEAD RESTRAINT CHILD SEAT RESTRAINTS CHILD SEAT INTERIOR LOOSE OBJECT OTHER OCCUPANT(S)	(61) (72) MISCELL (00) (38) (90) (96) (97)	OTHER VEHICLE OBJECTS (DESCRIBE) ANEOUS NO CONTACT (INVALID FIELD FORM CODE) OTHER (E.G. FIRE. DESCRIBE) SPARE TIRE INDUCED EJECTEB, UNKNOWN CONTACT
主	(34) (87) (47) (46) (48) (30) (42) (43) (31) (32) (52)	RESTRAINT SYSTEM WEBBING AIR CUSHION SKIN (AIRBAG) AIRBAG (ACRS) COMPARTMENT DOOR/COVER AIRBAG GAS KNEE RESTRAINT HEAD RESTRAINT CHILD SEAT RESTRAINTS CHILD SEAT INTERIOR LOOSE OBJECT OTHER OCCUPANT(S) INTERNAL FLYING GLASS (FROM ANY SOURCE)	(61) (72) MISCELL (00) (38) (90) (96) (97)	OTHER VEHICLE OBJECTS (DESCRIBE) ANEOUS NO CONTACT (INVALID FIELD FORM CODE) OTHER (E.G. FIRE. DESCRIBE) SPARE TIRE INDUCED EJECTEB, UNKNOWN CONTACT IMPACT FORCE, "WHIPLASH",
主	(34) (87) (47) (46) (48) (30) (42) (43) (31) (32) (52)	RESTRAINT SYSTEM WEBBING AIR CUSHION SKIN (AIRBAG) AIRBAG (ACRS) COMPARTMENT DOOR/COVER AIRBAG GAS KNEE RESTRAINT HEAD RESTRAINT CHILD SEAT RESTRAINTS CHILD SEAT INTERIOR LOOSE OBJECT OTHER OCCUPANT(S)	(61) (72) MISCELL (00) (38) (90) (96) (97) (98)	OTHER VEHICLE OBJECTS (DESCRIBE) ANEOUS NO CONTACT (INVALID FIELD FORM CODE) OTHER (E.G. FIRE. DESCRIBE) SPARE TIRE INDUCED EJECTEB, UNKNOWN CONTACT



INJURY CLASSIFICATION IC-4

CODES FOR OCCUPANT INJURY CLASSIFICATION (OIC)

	CODES FOR OCCUPANT INJURY CLASSIFICATION (OIC)									
1	BODY REGION	3	L	ESIOI	N	4	SYSTEM/ORGAN			
	(H) HEAD/SKULL		(L) LACE	ACERATION		(S) SKELETAL			
	(F) FACE		(C) CON	TUSION		(V) VERTEBRAE			
	(N) NECK		(A) ABR	ASION		(J) JOINTS			
	(S) SHOULDER		(F) FRAC	CTURE		(D) DIGESTIVE			
	(X) UPPER EXTREMITIES				FORATION, CTURE		(L) LIVER			
	(A) ARM (UPPER)				CUSSION		(N) NERVOUS SYSTEM			
	(E) ELBOW) AVUI			(B) BRAIN			
	(R) FOREARM			, AVO.			(C) SPINAL CORD			
	(W) WRIST/HAND			,) SPR/			(E) EARS			
	(C) CHEST		•		LOCATION		(O) EYES			
	(M) ABDOMEN			CRUS			(A) ARTERIES			
	(B) BACK						(H) HEART			
	(P) PELVIC/HIP			BURN			(Q) SPLEEN			
	(Y) LOWER EXTREMITIES				CHMENT,		(G) UROGENITAL			
	(T) THIGH				RATION		(K) KIDNEYS			
	(K) KNEE (L) LEG (LOWER)		(Z)	Z) FRACTURE AND DISLOCATION			(R) RESPIRATORY			
			(T)	STRA	RAIN		(P) PULMONARY/LUNGS			
	(Q) ANKLE/FOOT		(E)	TOTA	L SEVERANCE,		(M) MUSCLES			
-	(O) WHOLE BODY			TRAN	SECTION		(T) THYROID, OTHER ENDOCRINE GLAND			
	(U) UNKNOWN		(O) OTHER (U) UNKNOWN				(I) INTEGUMENTARY (SKIN)			
							(W) ALL SYSTEMS IN REGION			
							(U) UNKNOWN			
							•			
_										
2	ASPECT			-	•	5	SEVERITY			
	(R) RIGHT			SYS			(OR "AIS", ABBREVIATED INJURY SCALE)			
	(L) LEFT	η γ _α		TEN.	ထ္ဆ		(0) NONE			
	(R) RIGHT (L) LEFT (B) BILATERAL (C) CENTRAL		ASDECT	SYSTEM/ORGAN	SEVERITY		(1) MINOR			
	(C) CENTRAL	2 2	3 9	ŽŽ	Ĩ		(2) MODERATE			
	(A) ANTERIOR/FRONT	1 2	2 (3 4	5		(3) SERIOUS			
	(P) POSTERIOR/BACK						(4) SEVERE			
	(S) SUPERIOR/UPPER						(5) CRITICAL			
	(I) INFERIOR/LOWER					•	(6) MAXIMUM			
>	(W) WHOLE REGION				- -		(9) UNKNOWN			

主

(U) UNKNOWN



N 20300#1





Available











t Availabl



est Availabl



st Availab



Availabl





lest Availab





















120300#23



J 20300 #24









N 20300 #28





4.20300 #30

















































N 20300 #54